

ASS. REC. BY:

REF:

LIP / CS/AGI24070082/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SMG 4941S

Policy No.

Claims No. C10030309/HY

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / En not ready

519 L1 Rm & 3300b Calw (red 12,989.68, 79%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Repair Estimate

Not Authorized
11/8/24 \$3300k

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Accuracy After Pain
4 days

Make/Model: VOLKSWAGEN TOURAN

Date: 16/08/2024

Engine/Chassis No.: WVGZZZ1TZW074634

Claim Type: TP

Date of accident: 01.07.24

VRN: SFE8778P

Damaged area: Rear

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 2,250.00	\$ 2,250.00
2	Tailgate lock	1	\$ 335.00	\$ 335.00
3	Tailgate lock sensor	1	\$ 320.00	\$ 320.00
4	Tailgate weatherstrip	1	\$ 221.00	\$ 221.00
5	Tailgate 'VW' logo	1	\$ 99.70	\$ 99.70
6	Tailgate 'TOURAN' emblem	1	\$ 79.80	\$ 79.80
7	Tailgate inner trim	1	\$ 745.00	\$ 745.00
8	Tailgate lower chrome moulding	1	\$ 385.00	\$ 385.00
9	Tailgate lamp	2	\$ 598.00	\$ 1,196.00
10	Rear windscreen moulding	1	\$ 194.00	\$ 194.00
11	Rear bumper	1	\$ 1,399.00	\$ 1,399.00
12	Rear bumper lower	1	\$ 776.00	\$ 776.00
13	Rear bumper side retainer	2	\$ 168.00	\$ 336.00
14	Rear bumper reinforcement	1	\$ 691.70	\$ 691.70
15	Rear bumper inner bracket 184	1	\$ 361.50	\$ 361.50
16	Rear bumper reflector	2	\$ 289.00	\$ 578.00
17	Rear bumper reflector bracket	2	\$ 105.00	\$ 210.00
18	Rear bumper tow cover	1	\$ 89.50	\$ 89.50
19	Taillamp	2	\$ 689.00	\$ 1,378.00
20	Taillamp panel	2	\$ 165.00	\$ 330.00
21	Tailgate 'TSI' emblem	1	\$ 75.00	\$ 75.00
22	Tailgate stopper	2	\$ 18.00	\$ 36.00
23	End panel	1	\$ 685.00	\$ 685.00
24	End panel top garnish	1	\$ 284.00	\$ 284.00
Subtotal				\$ 13,055.20
List discount				10.00%
Total				\$ 11,749.68

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate inner trim clips	10	\$ 5.50	\$ 55.00
2	Rear bumper clips	12	\$ 5.50	\$ 66.00
3	Reverse camera	1	\$ 450.00	\$ 450.00

Repair Estimate

4	Rear licence plate & frame	Sm	1	\$ 55.00	\$ 55.00	X
5	End panel sealant	na	1	\$ 80.00	\$ 80.00	X
6	Rear windscreen sealant	na	1	\$ 80.00	\$ 80.00	X
7	Reverse sensor	add/short	2	\$ 280.00	\$ 560.00	200sm
8	Taillamp panel sealant	na	1	\$ 100.00	\$ 100.00	X
9	End panel top garnish clips	na	8	\$ 5.50	\$ 44.00	X
10	Sundries	na	1	\$ 50.00	\$ 50.00	X
				Total	\$ 1,540.00	

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ na 100.00
4	To rust proof all affected portions after repair.	0.5	\$ na 100.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ na 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
Total labour			\$ 3,000.00

Estimate Grand Total	\$ 16,289.68
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: