

Date : 29-Jun-2024

Vehicle Num : SLU4363Z

Make/Model : JAGUAR / XE 2.0 I4P TSS

Chassis No : SAJAB4AG3HA965332

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear bumper	1	\$ 3,802.50	\$ 3,802.50
2	Rear bumper bracket Lh X	1	\$ 98.02	\$ 98.02
3	Rear bumper bracket Rh ?	1	\$ 98.02	\$ 98.02
4	Rear bumper center bracket ?	1	\$ 422.55	\$ 422.55
5	Rear bumper cover cap Lh X	1	\$ 42.75	\$ 42.75
6	Rear bumper cover cap Rh ?	1	\$ 42.75	\$ 42.75
7	Rear lower spoiler Re / pluh	1	\$ 1,352.11	\$ 1,352.11
8	Rear bumper under cover X	1	\$ 676.59	\$ 676.59
9	Rear towing cap X	1	\$ 51.36	\$ 51.36
10	Rear reinforcement ?	1	\$ 1,267.50	\$ 1,267.50
11	Rear parking sensor ?	1 / 4	\$ 253.59	\$ 1,014.36
	Total Parts			\$ 8,868.51
	Less 10%			\$ 886.85
	TOTAL AMOUNT			\$ 7,981.66
	MISCELLANEOUS ITEM			
1	Sundries		\$ 25.00	\$ 20 25.00
2	Rear bumper clips	10	\$ 3.00	\$ 30.00 30.00
	LABOUR			
1	To remove and refitting rear bumper, rear reinforcement and each other.		\$ 640.00	\$ 250 640.00
2	Surface preparation, spray paint and polish rear bumper, rear panel and other affected areas.		\$ 500.00	\$ 250 500.00
3	To perform diagnosis check		\$ 80.00	\$ 60 80.00
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	Third party survey is on a "Without Prejudice" basis			
	TOTAL		\$ 1,220.00	\$ 9,256.66
	GST 9%			\$ 833.10
	GRAND TOTAL			\$ 10,089.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: