



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070085/Aqh3
75 BRAS BASAH ROAD	Date:	25/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 3867J	Veh. Inspected	SMF 8957B
Policy No.	-	Coverage	0
Claim No.	MT/1284194-002	Excess	\$0.00
Assign From	BILLY TAN	Assign Date	04/07/2024

2. Vehicle Details

Make & Model	MAZDA 3	C.C	1496
Engine No.	P520552567	Year of Reg.	28/11/2018
Chassis No.	JM6BN24A8K0252676	Colour	BLUE
Odometer	85460 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60 R16	YOKOHAMA	6
L/H Front Tyre	205/60 R16	YOKOHAMA	6
R/H Rear Tyre	205/60 R16	YOKOHAMA	6
L/H Rear Tyre	205/60 R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/06/2024	Inspection Date	08/07/2024 (12:28)
Survey held at	MG SOLUTION PTE LTD - 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days