

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 67444986 Fax: 67444165

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT	<i>Xiao Chen</i>
DATE:	08-07-24	
CLAIM TYPE:	T/P CLAIM	
TO:	INCOME	
VEHICLE DETAILS		
VEHICLE NO:	SMF8975B <i>SMF8957B.</i>	<i>JM6BN24A8K0252676</i>
MAKE & MODEL:	MAZDA 3	
CHASSIS NO:		
ACCIDENT DETAILS		
DATE:	29 June, 2024	
TIME:	1100HRS	
THIRD PARTY REQUESTOR:	JACK LI	

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Defect</i>	1	\$ 1,088.20	\$ 1,088.20
2	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.40	\$ 124.80
3	REAR BUMPER REFLECTOR <i>lit could</i>	2	\$ 110.00	\$ 220.00
4	REAR BUMPER REINFORCEMENT <i>Defect</i>	1	\$ 620.00	\$ 620.00
5	REAR BUMPER TOWING COVER <i>Missing lit</i>	2	\$ 85.00	\$ 170.00
6	REAR BUMPER CENTRE HOLDER <i>Defect</i>	1	\$ 80.00	\$ 80.00
7	REAR BUMPER EXHAUST PIPE COVER <i>Missing</i>	1	\$ 130.00	\$ 130.00
8	REAR TAILLAMP <i>New</i>	2	\$ 930.00	\$ 1,860.00
9	REAR END PANEL <i>New Reins</i>	1	\$ 620.00	\$ 620.00
10	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 220.00	\$ 220.00

TOTAL PRICE \$ 5,133.00

LESS 20% \$ 1,026.60

SUB TOTAL PRICE \$ 4,106.40

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER CLIPS SET <i>New</i>	1	\$ 20.00	\$ 20.00
2	REAR END PANEL TOP GARNISH CLIPS SET <i>New</i>	1	\$ 20.00	\$ 20.00
3	REAR END PANEL INSULATION SEALANT <i>New</i>	1	\$ 120.00	\$ 120.00
4	REVERSE SENSOR <i>Defect</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 380.00

220

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,000.00	\$ 1,000.00	300
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00	800
3	TUFF COAT	1	\$ 200.00	\$ 200.00	30
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	x
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00	x
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	50

TOTAL \$ 2,660.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	4,486.40
TOTAL LABOUR COST	\$	2,660.00
TOTAL REPAIR COST	\$	7,146.40

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adnan
L/S 08/07/24
03 days.

Total: 2743.36

L/S : 22K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: