

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035020
Oh Mwee Choo

Page 1 of 2
Your ref. TP-YP 2500E Lonpac
Job No. 74503
Our ref. 24.06.10
Payment
Date 10/6/2024

Attn

Vehicle No SBU 338S
Vehicle Model : Mercedes Benz A180
Accident on ... 7/6/2024

NOT WITHIN

Resurvey BY paint

7 days

89692-20

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts-Nett item:					
1.00	Pc	Front fender RH	795.00	10.00	715.50
1.00	Pc	Front door RH	2,055.00	10.00	1,849.50
1.00	Pc	Front door weatherstrip RH	360.00	10.00	324.00
1.00	Pc	Front door sound insulation RH	90.00	10.00	81.00
1.00	Pc	Front door wing mirror RH	960.00	10.00	864.00
1.00	Pc	Front door wing mirror cover RH	283.00	10.00	254.70
1.00	Pc	Front door wing mirror glass RH	630.00	10.00	567.00
1.00	Pc	Rear door RH	2,405.00	10.00	2,164.50
1.00	Pc	Rear door weatherstrip RH	360.00	10.00	324.00
1.00	Pc	Rear door sound insulation RH	90.00	10.00	81.00
Labour & Misc:					
1.00		To check/clear fault codes after repair	120.00		120.00
1.00		Computerised wheel alignment	60.00		60.00
1.00		To straighten body, to knock dents on rear	1,000.00		1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035020
Oh Mwee Choo

Page: 2 of 2
Your ref.: TP-YP 2500E Lonpac
Job No.: 74503
Our ref: 24.06.10
Payment
Date: 10/6/2024

Attn

Vehicle No: SBU 338S
Vehicle Model : Mercedes Benz A180
Accident on ...: 7/6/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		fender RH, to repair front bumper and renew parts			
1.00		To spray paint (including front sport rim RH)	1,500.00		1,500.00

1300/-

Sub-Total 9,905.20
GST 9.00% 891.47
Total S\$ 10,796.67

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."