

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD Ref: CS3/FCI24060040/Evp3				
INIS		INSURANCE LTD		·
	16 RAFFLES QUAY #42-01 HONG LEON	G BUILDING	Date:	16/07/2024
			Code:	FCI2
1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SHD 7120A	Veh. Inspected	FBC 1919D
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24005066MFCT	Excess	\$0.00
	Assign From	AINI	Assign Date	11/06/2024
2. Vehicle Details				
	Make & Model	YAMAHA AEROX155 ABS CVT	C.C	155
	Engine No.	G3P4E0028382	Year of Reg.	10/11/2021
	Chassis No.	MH3SG6420MJ016821	Colour	BLUE
	Odometer	56121 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	FAIR
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	<b>Size</b> 110/70 R13	Make BRIDGESTONE	Balance (mm) 5
	R/H Front Tyre L/H Front Tyre			, ,
				, ,
	L/H Front Tyre	110/70 R13	BRIDGESTONE	5
4.	L/H Front Tyre R/H Rear Tyre	110/70 R13	BRIDGESTONE BRIDGESTONE	5
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	110/70 R13 130/70 R13	BRIDGESTONE BRIDGESTONE	5
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	110/70 R13 130/70 R13 Description of	BRIDGESTONE BRIDGESTONE Damages	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	110/70 R13  130/70 R13  Description of DAMAGES AT THE FRONT PORTION.	BRIDGESTONE BRIDGESTONE Damages	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINED	110/70 R13  130/70 R13  Description of DAMAGES AT THE FRONT PORTION.  General Info	BRIDGESTONE BRIDGESTONE Damages rmation Inspection Date	5 12/06/2024
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINED Accident Date	110/70 R13  130/70 R13  Description of DAMAGES AT THE FRONT PORTION.  General Info	BRIDGESTONE BRIDGESTONE Damages  rmation Inspection Date 4 #01-16 BARTLEY B	5 12/06/2024
5a. A) THE B) TH THE C) EI D) M	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINED Accident Date Survey held at HE INSPECTION WASHE REPAIR ESTIMATE REPAIRER WAS TOLE NCLOSED PLEASE FI ARKET VALUE:\$11,50	Description of D DAMAGES AT THE FRONT PORTION.  General Info 04/06/2024 HOTGEARZ SG 13 KAKI BUKIT ROAD 4 Remar CONDUCTED ON A "WITHOUT PREJUE WAS NOT PRESENTED AT THE TIME.D TO PREPARE THE ESTIMATE. ND DAMAGED VEHICLE PHOTOGRAPH	BRIDGESTONE  BRIDGESTONE  BRIDGESTONE  Damages  Trmation Inspection Date 4 #01-16 BARTLEY B  ks  DICE" BASIS. OF INSPECTION.	5 5 12/06/2024 IZ CENTRE S
5a. A) THE B) TH THE C) EI D) M	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINED Accident Date Survey held at HE INSPECTION WASHE REPAIR ESTIMATE REPAIRER WAS TOLE NCLOSED PLEASE FI ARKET VALUE:\$11,50	Description of D DAMAGES AT THE FRONT PORTION.  General Info 04/06/2024 HOTGEARZ SG 13 KAKI BUKIT ROAD 4 Remar CONDUCTED ON A "WITHOUT PREJUE WAS NOT PRESENTED AT THE TIME.D TO PREPARE THE ESTIMATE. ND DAMAGED VEHICLE PHOTOGRAPH 00.00 (EST)	BRIDGESTONE  BRIDGESTONE  BRIDGESTONE  Damages  Fraction Inspection Date 4 #01-16 BARTLEY B  ks  DICE" BASIS. OF INSPECTION.  IS.  IS IN THE REGION C	5 5 12/06/2024 IZ CENTRE S

## CTY

## CHEN TSUE YEE