Our Ref:	GBL6863A240628		Date: 14/07/2024
Your Ref:	D24005738MFCT/CTPL/TPD2		
16 Raffles Qua Hong Leong E Singapore 048	Building 3581 S Department		
Traffic Accident Involving	dent Along Towards Upper Changi Road North GBL6863A and SHA5995X On 28/06/2024	4	
m/vehicle - by "	dbell Leasing Pte Ltd (NRIC / ROC No: 19 GBL6863A at all material times of the ab authorized appraiser and we/I based -00 w/GST being the repair for05Days (Str	ove accident. Out	r/my vehicle was surveyed on his recommendation
•	ascertained that you were the insurers of the drinvolved in the aforesaid accident with our/my m	•	
solely by th	eby you are the insurers of m/vehicle <u>SHA5995X</u> e negligence of your insured and as a result thered loss and damage as follows:		•
	e-repair notice 02 days @ \$\$ _80-00 [2982 cc] r 05 days @\$\$ _80-00 [2982 cc]	S\$	4,142-00 w/GST 160-00 400-00
GIA / LTA s			2-18
Total Amou	int	S\$	4,704-18
(i)	se herewith copies of the supporting documents Motor Accident Report & Documents; Repair Invoices;	for vehicle no	GBL6863Aas follows:-
Kindly look as possible.	into the matter and let us/me hear from you or	n the settlement	of our/my claims as soon
	it us/me your settlement sum in favor of M/s l o. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kal		

Yours faithfully,

/	
The owner of m/vehicle ₋	GBL6863A
Messers <u>Goldbell Leasing</u>	
cc. Liu's Bro Auto Works	shop

Tel: 67411730

14/07/2024

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

FINAL BILL

GBL6863A240628

Name: MS First Capital Insurance Limited

Addres: Motor Claims Department

16 Raffles Quay #42-01 Hong Leong Building Sing

Singapore 048581

Ref Date: Ref No:

Vehicle No: GBL6863A Model / Make: Toyota Hiace

Capacity: 2982 cc Van Turbo 5 DR MT

Item #	Damaged Area	Description	Uı	nit Price	Qty	imation / uotation	N / SN	Cost Of Repair
1	Rear	Tailgate	\$:	2,159.30	1	\$ 2,159.30		\$ -
2		Tailgate Inner Lock	\$	399.20	1	\$ 399.20		\$ -
3		Tailgate Weatherstrip	\$	388.50	1	\$ 388.50		\$ -
4		Tailgate "Toyota" Motif	\$	70.50	1	\$ 70.50		\$ -
5		Tailgate "70 KM/H" Sticker	\$	15.00	1	\$ 15.00	SN	\$ -
6		Tailgate "8 PAX" Sticker	\$	15.00	1	\$ 15.00	SN	\$ -
7		Tailgate Windscreen Glass	\$	1,102.30	1	\$ 1,102.30		\$ -
8		Tailgate Windscreen Glass Sealant	\$	40.00	1	\$ 40.00	SN	\$ -
9		Bumper	\$	681.40	1	\$ 681.40		\$ -
10		Bumper Clips 1 set	\$	65.00	1	\$ 65.00	SN	\$ -
11		Bumper Reverse Sensor	\$	220.00	1	\$ 220.00	SN	\$ -
12		End Panel Outer	\$	665.20	1	\$ 665.20		\$ -
13		End Panel Inner	\$	795.40	1	\$ 795.40		\$ -
14		End Panel Sealant	\$	50.00	1	\$ 50.00	SN	\$ -
15		"Corporate" Advertisement & Artwork				\$ 400.00	SN	\$ -
16		Remove and refix rear bumper reverse sensor				\$ 80.00		\$ -
17		Remove & reinstall Tailgate Glass to facilitate repairs				\$ 120.00		\$ -
18		Remove and refix rear tailgate components & wiper mechanism				\$ 100.00		\$ -
19		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs				\$ 800.00		\$ -
20		To putty & spray painting & including touch up paint on accident affected areas				\$ 600.00		\$ -
21		To apply Rust Proofing , reseal tuff-coating treatment on accident area				\$ 80.00		\$ -

Total Parts & Labour of estimate for damaged vehicle	Sub-Total	\$ 8,846.80

Total amount in Lumpsum Basis for repaired vehicle
GST TAX

9.00%

\$ 3,800.00
\$ 342.00

Grand Total \$ 9,643.01 \$ 4,142.00

SDL Four Thousand One Hundred Forty-Two Only w/GST



INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SHA5995X

Date of Accident

28/06/2024 🛗

Reset

% RESULT & RECEIPT

Payment details
Request Amount: \$\$2
GST Amount: \$\$0.18

Total Amount Due (GST Inclusive): \$\$2.18

General Insurance Association
Records Management Centre
GST Registration No: M400017735

1 of 1 3/7/2024, 9:07 am