

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

*NTUC*

Name : Keoh Kim Chai (84252560)

Accident Date : 29-Jun-24

Vehicle No : JTV2425 (DOR: 06012020)

Vehicle Model : Yamaha YZF-R25

## Estimated Repair Costs

| Qty | Description<br><u>List Items</u>          | Amount S(\$)             |
|-----|-------------------------------------------|--------------------------|
| 1   | Fork tube assy - L/H <i>SCC</i>           | \$ 980.00 X              |
| 1   | Fork tube assy - R/H <i>SCC</i>           | \$ 980.00 X              |
| 1   | Fork under bracket <i>u7</i>              | \$ 480.00 X              |
| 1   | Front rim <i>u7</i>                       | \$ 750.00 X              |
| 1   | Front rim shaft <i>u7</i>                 | \$ 145.00 X              |
| 1   | Front rim bearing <i>u7</i>               | \$ 90.00 X               |
| 1   | Headlamp assy <i>CN</i>                   | 900 \$ 1,180.00 ✓        |
| 1   | Headlamp cover <i>black CN</i>            | 200 \$ 245.00 ✓          |
| 1   | Lampstay <i>R</i>                         | \$ 485.00 X              |
| 1   | Handle-bar - L/R/H <i>SCC</i>             | \$ 522.00 X              |
| 1   | Hand grip <i>SCC</i>                      | \$ 108.00 X              |
| 1   | Handle bar end <i>CN</i>                  | 50 \$ 160.00 ✓           |
| 2   | Mirror - L/R/H <i>u7</i>                  | 110 \$ 420.00 <i>120</i> |
| 1   | Front signal (1 set) <i>CN</i>            | 110 \$ 180.00 ✓          |
| 1   | Brake lever <i>CN</i>                     | 105 \$ 160.00 ✓          |
| 1   | Brake pedal <i>CN</i>                     | 160 \$ 220.00 ✓          |
| 1   | Front footrest - R/H <i>CN</i>            | 148 \$ 230.00 ✓          |
| 1   | Front footrest bracket - R/H <i>u7</i>    | \$ 380.00 X              |
| 1   | Rear footrest - R/H <i>CN</i>             | 148 \$ 200.00 ✓          |
| 1   | Rear footrest bracket - R/H <i>u7</i>     | \$ 250.00 X              |
| 1   | Exhaust pipe <i>CN</i> <i>1500</i>        | \$ 2,200.00 ✓            |
| 2/1 | Rear rim <i>SCC</i>                       | \$ 880.00 X              |
| 1   | Rear rim shaft <i>SCC</i>                 | \$ 165.00 X              |
| 1   | Rear Brake disc <i>u7</i>                 | \$ 320.00 X              |
| 1   | Rear swing arm <i>R2 cone</i> <i>1500</i> | \$ 980.00 X              |
| 1   | Fairing assy (1 set) <i>CN/CN</i>         | 980 \$ 2,800.00 ✓        |
|     |                                           | \$ 15,510.00             |
|     |                                           | Less 10% \$ 1,551.00     |
|     |                                           | \$ 13,959.00             |

*No. of Accident  
all  
missing*

*4/7/24*

*2/5/2000  
the p.h. Asher*

*4/7/24*

