

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2400974

INV Date : 14-10-2024

Reference CD/LPC24070088/Rma3

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKF 8769B
Insured Veh. SML 1840T
Claim No. 24/24/24/VP05/029449
Policy No. Z24VP05035197
Accident Date 27/06/2024
Inspection Date 10/07/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24070088/Rma3
300 BEACH ROAD	Date:	14/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SML 1840T	Veh. Inspected	SKF 8769B
Policy No.	Z24VP05035197	Coverage	0
Claim No.	24/24/24/VP05/029449	Excess	\$0.00
Assign From	GERALD POH	Assign Date	04/07/2024

2. Vehicle Details

Make & Model	B.M.W 216I GRAN TOURER	C.C	1499
Engine No.	40875705B38A15A	Year of Reg.	20/08/2019
Chassis No.	WBA6V120405N59243	Colour	GREY
Odometer	55774 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R17	BRIDGESTONE	6
L/H Front Tyre	205/55 R17	BRIDGESTONE	6
R/H Rear Tyre	205/55 R17	BRIDGESTONE	6
L/H Rear Tyre	205/55 R17	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/06/2024	Inspection Date	10/07/2024
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKF 8769B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR LH	BENT	\$1,480.00	\$1,480.00
1	FRONT DOOR WEATHERSTRIP	NECESSARY	\$70.00	\$70.00
1	FRONT DOOR OUTER HANDLE LH	TO REPAIR SEE LABOUR	\$170.00	\$0.00
1	FRONT DOOR HANDLE KNOB LH	NOT NECESSARY	\$80.00	\$0.00
1	REAR DOOR LH	BENT	\$1,580.00	\$1,580.00
1	REAR DOOR WEATHERSTRIP LH	NECESSARY	\$70.00	\$70.00
1	REAR DOOR OUTER HANDLE LH	NOT NECESSARY	\$170.00	\$0.00
1	REAR DOOR HANDLE KNOB LH	NOT NECESSARY	\$80.00	\$0.00
1	SIDE SKIRT LH	TO REPAIR SEE LABOUR	\$420.00	\$0.00
1	SIDE ROCKER PANEL LH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	FRT DOOR GLASS REGULATOR LH (NPA)	NOT NECESSARY	\$0.00	\$0.00
1	FRT DOOR GLASS MOTOR LH (NPA)	NOT NECESSARY	\$0.00	\$0.00
	LESS 5.00% DISCOUNT		(\$206.00)	(\$160.00)
			\$3,914.00	\$3,040.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TYRE RIM LH (SN)	CUT	\$380.00	\$300.00
			\$380.00	\$300.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CUT ,WELD PANEL BEAT,STRAIGHTEN ,REPLACE DAMAGED PARTS & REALIGN AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER HANDLE LH,SIDE SKIRT LH,SIDE ROCKER PANEL LH,REAR FENDER LH AND REAR BUMPER.		\$1,000.00	\$600.00
	TO PUTTY SPRAY PAINT ON FRT DOOR LH ,REAR DOOR LH,REAR FENDER LH ,REAR BUMPER ,SIDE SKIRT LH ,SIDE ROCKER PANEL LH ,FRT DOOR HANDLE LH		\$1,200.00	\$800.00
	TO CHECK STEERING GEOMETRY & CONTROL WHEEL ALIGNMENT		\$100.00	\$60.00
	TO CONDUCT ADAS SYSTEM PROGRAMMING		\$380.00	\$150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT FRT DOOR MECHANISM & OTHER ATTACHMENT PARTS		\$150.00	\$60.00
	TO REMOVE & REFIT REAR DOOR MECHANISM & OTHER ATTACHMENT PARTS		\$150.00	\$60.00
			\$2,980.00	\$1,730.00
GRAND TOTAL			\$7,274.00	\$5,070.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$4,000.00
Report Ref No: CD/LPC24070088/Rma3				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B



PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SKF 8769B

