

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# ESTIMATE

3/7/2024

**LONPAC INSURANCE BHD**  
300 BEACH ROAD  
17-04/07 THE CONCOURSE  
SINGAPORE 199555

Vehicle No: SKF8769B  
Vehicle Model: BMW216I  
Est No:CBMQ24070039  
Claims ref:  
Accident Date: 27/06/24  
In Charge: JUNIOR  
Remarks:

| No                        | Description                       | Qty | U. Price       | Amounts S\$        |
|---------------------------|-----------------------------------|-----|----------------|--------------------|
| <b>LIST ITEMS:</b>        |                                   |     |                |                    |
| 1                         | FRONT DOOR LH                     | 1   | PC \$ 1,480.00 | \$ 1,480.00        |
| 2                         | FRONT DOOR WEATHERSTRIP           | 1   | PC \$ 70.00    | \$ 70.00           |
| 3                         | FRONT DOOR OUTER HANDLE LH        | 1   | PC \$ 170.00   | \$ 170.00          |
| 4                         | FRONT DOOR HANDLE KNOB LH         | 1   | PC \$ 80.00    | \$ 80.00           |
| 5                         | REAR DOOR LH                      | 1   | PC \$ 1,580.00 | \$ 1,580.00        |
| 6                         | REAR DOOR WEATHERSTRIP LH         | 1   | PC \$ 70.00    | \$ 70.00           |
| 7                         | REAR DOOR OUTER HANDLE LH         | 1   | PC \$ 170.00   | \$ 170.00          |
| 8                         | REAR DOOR HANDLE KNOB LH          | 1   | PC \$ 80.00    | \$ 80.00           |
| 9                         | SIDE SKIRT LH                     | 1   | PC \$ 420.00   | \$ 420.00          |
| 10                        | SIDE ROCKER PANEL LH - REPAIR     | 1   | PC             | \$ -               |
| 11                        | REAR FENDER LH - REPAIR           | 1   | PC             | \$ -               |
| 12                        | REAR BUMPER - REPAIR              | 1   | PC             | \$ -               |
| 13                        | FRT DOOR GLASS REGULATOR LH-CHECK | 1   | PC             | \$ -               |
| 14                        | FRT DOOR GLASS MOTOR LH - CHECK   | 1   | PC             | \$ -               |
| LIST TOTAL S\$            |                                   |     |                | \$ 4,120.00        |
| 5% DISCOUNT S\$           |                                   |     |                | \$ (206.00)        |
|                           |                                   |     |                | <u>\$ 3,914.00</u> |
| <b>SPECIAL NET ITEMS:</b> |                                   |     |                |                    |
| 1                         | REAR TYRE RIM LH                  | 1   | PC \$ 380.00   | \$ 380.00          |
| SPECIAL NET TOTAL S\$     |                                   |     |                | <u>\$ 380.00</u>   |

**LABOUR CHARGE:**

|   |                                                                                    |             |
|---|------------------------------------------------------------------------------------|-------------|
| 1 | TO CUT,WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREA | \$ 1,000.00 |
| 2 | TO PUTTY SPRAY PAINT ON FRT DOOR LH, REAR DOOR LH,                                 |             |

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# ESTIMATE

3/7/2024

**LONPAC INSURANCE BHD**  
300 BEACH ROAD  
17-04/07 THE CONCOURSE  
SINGAPORE 199555

Vehicle No: SKF8769B

Vehicle Model: BMW216I

Est No:CBMQ24070039

Claims ref:

Accident Date: 27/06/24

In Charge: JUNIOR

Remarks:

| No                    | Description                                                                             | Qty | U. Price | Amounts S\$        |
|-----------------------|-----------------------------------------------------------------------------------------|-----|----------|--------------------|
|                       | REAR FENDER LH, REAR BUMPER, SIDE SKIRT LH, SIDE ROCKER<br>PANEL LH, FRT DOOR HANDLE LH |     |          | \$ 1,200.00        |
| 3                     | TO CHECK STEERING GEOMENTARY & CONDUCT WHEEL<br>ALIGNMENT                               |     |          | \$ 100.00          |
| 4                     | TO CONDUCT ADAS SYSTEM PROGRAMMING                                                      |     |          | \$ 380.00          |
| 5                     | TO REMOVE & REFIT FRT DOOR MECHANIMS & OTHER<br>ATTACHMENT PARTS                        |     |          | \$ 150.00          |
| 4                     | TO REMOVE & REFIT REAR DOOR MECHANISM & OTHER<br>ATTACHMENT PARTS                       |     |          | \$ 150.00          |
| TOTAL LABOUR COST S\$ |                                                                                         |     |          | <u>\$ 2,980.00</u> |

AMOUNT S\$ \$ 7,274.00  
GST @ 9% \$ 654.66  
AMOUNT DUE S\$ \$ 7,928.66

Customer's Signature

  
MOVA AUTOMOTIVE PTE LTD