

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5005M*Not Authorized*
618mp 82300h

AAD2201-011

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

04 JAN 2022

SHD5005M

VF1ABL15AUC283485

RENAULT

LATITUDE

31/12/2021

QBE

03/07/2017

PART		LIST	
1	BUMPER COVER FRT	\$	747.20 ✓
1	BUMPER ABSORBER FRT	\$	394.68 ✓
1	BUMPER RETAINER FRT LH	\$	101.40 ✓
1	BUMPER SUPPORT FRT	\$	10.70 X
1	BUMPER RETAINER FRT RH	\$	101.40 ✓
1	BUMPER SUPPORT FRT	\$	10.70 X
1	BUMPER UNDERTRAY FRT	\$	292.50 X
1	BUMPER SPOILER FRT	\$	344.70 X
1	BUMPER GRILLE LOWER FRT	\$	147.00 ✓
1	BUMPER BEAM FRT	\$	663.70 X
1	RADIATOR GRILLE	\$	969.90 ✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36 ✓
1	RADIATOR GRILLE FRAME	\$	686.00 X
1	FRAME FULL SUPPORT PANEL	\$	592.70 X
		\$	5,287.94
	10%	\$	528.79
		\$	4,759.15

Special Nett

1SET	BUMPER BRACKET CTR CLIP	\$	33.00 X
1	BUMPER CLIP FRT	\$	85.00 ✓
1	BUMPER RETAINER CLIP FRT	\$	70.00 X
1	BUMPER GRILLE LOWER CLIP	\$	70.00 X
1	LICENSE PLATE WITH HOLDER FRT	\$	120.00 450
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50 X
1SET	RADIATOR GRILLE SCREW	\$	16.00 X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00 X
	TOTAL	\$	473.50

Trans-cab Auto Services Pte Ltd**AAD2201-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5005M**TOTAL PARTS \$ 5,232.65****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101

TOTAL \$ 10,580.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5005M

AAD2201-011

Over All Total \$ 20,571.79

(LUMP SUM)

Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: