



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNH 843B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE	BENT	\$1,939.00	\$1,939.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	\$120.00	\$0.00
1	EMBLEM"HIGHWAY STAR"	NECESSARY	\$75.00	\$75.00
1	EMBLEM"E-POWER"	NECESSARY	\$105.00	\$105.00
1	TAILGATE STOPPER	SERVICEABLE	\$25.00	\$0.00
1	REAR BUMPER	CRACKED	\$1,575.00	\$1,575.00
10	REAR BUMPER CLIPS	NECESSARY	\$30.00	\$30.00
1	REAR BUMPER RETAINER	DISTORTED	\$45.00	\$45.00
1	RHR BUMPER GARNISH	* CHECK	\$400.00	\$0.00
1	RHR CORNER PANEL	SERVICEABLE	\$430.00	\$0.00
1	RHR CORNER PANEL BRACKET	* CHECK	\$45.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$240.00	\$0.00
1	REVERSE SENSOR	DENTED	\$280.00	\$280.00
4	SENSOR BRACKET	* CHECK	\$640.00	\$0.00
	LESS 10.00% DISCOUNT		(\$594.90)	(\$404.90)
			\$5,354.10	\$3,644.10
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SEALANT (SN)	NOT NECESSARY	\$40.00	\$0.00
			\$40.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL	NOT NECESSARY	\$750.00	\$400.00
	TO PUTTY,RESPRAY ON REAR BUMPER, REAR TAILGATE, RHR CORNER PANEL,REAR END PANEL, AFFECTED AREA		\$750.00	\$440.00
	TO REMOVE/REFIT REAR WINDSCREEN		\$120.00	\$0.00
	TO CHECK WIRING, RE-INSTALL REVERSE SENSOR		\$60.00	\$60.00
	TO TUFF COAT/WATER PROOFING ON WELD AREA		\$50.00	\$30.00
			\$1,730.00	\$930.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

<b>GRAND TOTAL</b>		<b>\$7,124.10</b>	<b>\$4,574.10</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$976.50 NETT)</b>		<b>\$4,574.10</b>
<b>Report Ref No: CS/FCI24070091/Knp3m4</b>			

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.