# **CENTURY MOTORS PRIVATE LIMITED INCHCAPE CENTRE SINGAPORE 128462**

**Insurer Reference: SMM5278K** 

**Full Report** Repairer Reference: CM217/SMM5278K **Registration: SMM5278K** Date calculated: 19/09/2024 12:16 PM Printed: 19/09/2024 12:16 PM

## **Summary Information**

Claim

Location: Singapore (SG) Work Provider: China Taiping Insurance

(Singapore) Pte Ltd

Printed by: SGD Lim Mei Hong Currency: Claim Reference: SMM5278K Date of Incident: 27/10/23

Hire Car Start: Estimated Repair Time: Actual Repair Days: Hire Car End:

#### **Vehicle Details**

Vehicle

Manufacturer: HONDA Model: **STREAM** 

Sub Model: LS

Model Sheet Number: 35 36 01 Registration: SMM5278K VIN number: GP72010632

Odometer: **Model Specs** 

PREPARE OFF VEHICLE TWO COAT METALLIC


## **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

## **Damage Areas**

ΑII **Underbody** 



## **Tyres Condition**

**Tyre Brand** Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Outer),

Condition

mm

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

#### Labour

	Time Base 10 WU/h	Price = 42.00 SGD/h
Code	Description	WU Price SGD
71101-S7A	RENEW FRONT BUMPER	5.0 21.00
0742	R/F WING REPAIR	Repair 5.0* / 21.00
	Labour Cost	Hrs WU
	Panel / Mechanical Labour	1.00 10.0 42.00
	Total of Labour	42.00

## **Paint**

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/F WING REPAIR PAINTING <50%	11.0

## **Paint Material Per Part**

Code

**Description** 

	•				
0742	R/F WING REPAIR PAINTING <50%				12.92
	Labour Cost - Paint	42.00.000.0	Hrs	wu	Price SGD
	Factor Time Paint	42.00 SGD/h		11.0	
	Preparation Main Work Metal		2.50	25.0	105.00
	Total	10 WU/h	3.60	36.0	151.20
	Material Cost - Paint				Price SGD
	Repair Painting				12.92
	Material-constant Metal Preparation				28.60
	Decreased by 90%				-37.37
	Total				4.15

## **Spare Parts**

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01 Price SGD
0283	FRONT BUMPER	71101S7AG00ZE	Original	700.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal			0.00 700.00
ar osca parts	Total			700.00

**Price SGD** 

## **Final Calculation**

	SGD	SGD
Parts Total Parts	700.00	700.00
Labour Time Base 10 WU/h Total 10.0 WU X 42.00 SGD/h Total of Labour	42.00	42.00
Paint Work Time Base 10 WU/h Labour Cost 36.0 WU X 42.00 SGD/h Material Cost Total Paint Including Material	151.20 4.15	155.35
Repair Cost Excludes GST		897.35
GST (+9.00%) Repair Cost Included GST		80.76 978.11
Deductions (Excludes GST) Repair Cost Discount (+20.00%) Total Of Deductions (Excludes GST)	-179.47	-179.47
Grand Total Excludes GST		717.88
GST (+9.00%) Grand Total Included GST		64.61 782.49

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

#### **Assessment Note**

No assessment notes entered.