



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070094/Eqp3e2
16 RAFFLES QUAY	Date:	04/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 8622L	Veh. Inspected	SNN 5935E
Policy No.	-	Coverage	0
Claim No.	D24005840MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	04/07/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS	C.C	1798
Engine No.	2ZRZ088389	Year of Reg.	18/12/2023
Chassis No.	MR2BZ3BE400013450	Colour	SILVER
Odometer	36308 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40 R17	DUNLOP	6
L/H Front Tyre	225/40 R17	DUNLOP	6
R/H Rear Tyre	225/40 R17	DUNLOP	6
L/H Rear Tyre	225/40 R17	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspection Date	04/07/2024
Survey held at	60 JALAN LAM HUAT #06-46/47 CARROS CENTRE S737869 - DING AUTO PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days