

Name & Address:

Motor Claims Department

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Type of Claim:

YEAR MODEL:

THIRD PARTY

22/09/2023

Vehicle No:

SNM4238X

Brand & Model:

BMW X1 sDrive16i M Sport

Chassis/VIN No:

WBA62EG0X05X62694

WIP#:

25107

Date:

4-Jul-24

Franchise:

BMW

Contact Person (Eurokars):

JOBI

Contact No (Eurokars):

6331 0680

REPAIR ESTIMATE

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER <i>Xan</i>	5112 5A4FFD3	1		-	\$ 1,265.65
2	REAR BUMPER COVER MID <i>sur repl</i>	5112 5A61950	1		-	\$ 364.35
3	COVER FOR TOWING <i>Xan</i>	51129881939	1		-	\$ 56.50
4	REAR BUMPER LOWER SPOILER <i>sur</i>	5112 5A4FFD5	1		-	\$ 205.70
5	BUMPER MOUNT LH <i>Xan</i>	51129881943	1		-	\$ 174.05
6	BUMPER MOUNT RH <i>? Xan</i>	51129881944	1		-	\$ 174.05
7	BUMPER MOUNT CORNER RH <i>? Xan</i>	51129883542	1		-	\$ 52.65
8	BUMPER MOUNT CENTER <i>? Xan</i>	51129883537	1		-	\$ 174.05
9	HOLDER SMO <i>? Xan</i>	51129883545	1		-	\$ 67.10
10	ABSORBER FUNNEL RH <i>? Xan</i>	51129881942	1		-	\$ 52.05
11	EXHAUST BUMPER TRIM RH <i>sur</i>	51128083650	1		-	\$ 53.15
12	KIT MOUNT PDC <i>Xan</i>	5112 5A4FFD7	1		-	\$ 67.90
13	EXPANDING RIVET <i>m</i>	51111908077	4		-	\$ 2.00
14	PLUG-IN NUT <i>? Xan</i>	51127461407	10		-	\$ 31.50
15	EXPANDING RIVET <i>m</i>	51777171004	24		-	\$ 34.80
16	REAR REINFORCEMENT <i>? Xan</i>	51129883546	1		-	\$ 534.50
17	WASHER-GASKET <i>Xan</i>	51127300789	2		-	\$ 23.10
18						\$ -

Sub-Total (Parts Price) \$ - \$ 3,333.10

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER, REAR REINFORCEMENT AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	850	\$ 2,225.00
2	TO RESPRAY REAR BUMPER.	1000	\$ 1,760.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		
5	SUNDRIES.	nett	\$ 500.00
		nett	\$ 20 50.00

Survey Date & Time:

05/07/24

Repair Days:

3 days

Excess:

Surveyor Remarks:

Repair Reg by post

Sub-Total (Labour Price) \$ - \$ 4,685.00

Parts Price

REVISED

PRICE

\$ - \$ 3,333.10