## **Bifrost Auto Pte Ltd**

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875 Tel: 93290237 Email: claims\_rar@bifrostauto.com

SJE:	Vehicle Nos :	SNJ 412B
Date of Survey :	Made:	Toyota
Date of ReSurvey:	Model:	Lexus ES250
Contacts:	Chassis No :	JTHB11B1602002887

## \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amou	nt:			Working Day:			
Nos.	PARTS	Qty		Unit S\$	TO	TOTAL S\$	
1	Front Bonnet V	1	\$	1,838.40	\$	1,838.40	
2	Front Bonnet Hinge RH X	1	\$	101.20	\$	101.20	
3	Front Bonnet Hinge LH	1	\$	101.20	\$	81.20	
4	Front Bonnet Lock X	1	\$	170.10	\$	170.10	
5	Front Bumper 🗴 🥀	1	\$	1,557.50	\$	1,557.50	
6	Front Bumper Number Plate Garnish 🏌	1	\$	141.60	\$	141.60	
7	Front Bumper Side Retainer RH 💢	1	\$	103.90	\$	103.90	
8	Front Bumper Side Retainer LH 💢	1	\$	103.90	\$	103.90	
9	Front Bumper Inner Sponge 🗡	1	\$	152.50	\$	152.50	
10	Front Bumper Reinforcement 🗡	1	\$	1,359.70	\$	1,359.70	
11	Front Bumper Tow Cover RH X	1	\$	73.10	\$	73.10	
12	Front Bumper Tow Cover LH 💢	1	\$	73.10	\$	73.10	
13	Front Bumper Fog Lamp Garnish RH X	1	\$	302.80	\$	302.80	
14	Front Bumper Fog Lamp Garnish LH 乂	1	\$	302.80	\$	302.80	
15	Front Bumper Bracket RH X	1	\$	161.10	\$	161.10	
16	Front Bumper Bracket LH X	1	\$	161.10	\$	161.10	
17	Front Grille Assembly X	1	\$	2,262.60	\$	2,262.60	
18	Front Grille Emblem X	1	\$	1,177.60	\$	1,177.60	
19	Front Headlamp Assembly RH / Per Science	1	\$	6,191.60	\$	6,191.60	
20	Front Headlamp Assembly LH X	1	\$	6,191.60	\$	6,191.60	
21	Front Support Panel 'X	1	\$	1,924.00	\$	1,924.00	
22	Front Support Panel Top Garnish .X	1	\$	247.50	\$	247.50	
23	Aircon Condenser 🛛 💢	1	\$	2,726.00	\$	2,726.00	
24	Radiator    ✓	1	\$	3,148.80	\$	3,148.80	
25	Front Fender RH / ()()	1	\$	2,416.50	\$	2,416.50	
26	Front Fender Inner Shield RH $ X $	1	\$	717.00	\$	717.00	
27	Front Wheel Rim RH / Repair Cost - Cut	1	\$	4,268.20	\$ 200	4,268.20	
28	Front Shock Absorber RH 🗸	1	\$	1,013.30	\$	1,013.30	
29	Front Lower Arm RH 🔏	1	\$	1,140.40	\$	1,140.40	
30	Front Knuckle Arm RH $^{\chi}$	1	\$	1,002.50	\$	1,002.50	
31	Front Wheel Bearing RH 🂢	1	\$	830.20	\$	830.20	
32	Front Door Side Mirror Assembly RH / / RR	1	\$ 1	2,150.40	\$	2,150.40	
33	Front Door Assembly RH . / BR	1	\$	3,043.80	\$	3,043.80	

Parts Sub Total : \$ 47,136.00

10% Discount \$ 4,713.60

PARTS TOTAL : \$ 42,422.40

Nos.	SPECIAL NETT	Qty	Unit S\$		Unit S\$		TOTAL S\$	
1	Front Number Plate X	1	\$	50.00	\$	50.		
2	Front Bumper Clips - Set X	1	\$	50.00	\$	50.		
3	Front Grille Assembly Clips - Set X	1	\$	50.00	\$	50.		
4	Front Headlamp Clips - Set X	1	\$	50.00	\$	50.		
5	Front Support Panel Top Garnish Clips - Set $X$	1	\$	30.00	\$	30.		
6	Front Fender Inner Shield Clips - Set 😾	1	\$	50.00	\$	50.		
7	Front Door Inner Trim Board RH Clips - Set <sup>X</sup>	1	\$	50.00	\$	50.		
8	Radiator Coolant X	1	\$	60.00	\$	60.		
9	Front Bonnet Sealant 💢	1	\$	150.00	\$	150.		
10	Front Support Panel Sealant 🗶	1	\$	150.00	\$	150.		
11	Front Fender RH Sealant 🗶	1	\$	150.00	\$	150.		
12	Front Door RH Sealant * / NRC	1	\$	150.00	\$	30 150.		
13	Front Tyre RH 💢	1	\$	500.00	\$	500.		
		SPEC	IAL	NETT TOTAL :	\$	1,490.		

Nos.	LABOUR		TOTAL S\$		
1	To Panel Beat, Remove & Refix Parts	\$ 500	2,000.00		
2	To Spray Paint Affected Areas	\$ 700	1,800.00		
3	Wiring & Bulb Check	\$ 30	100.00		
4	To Transfer Front Door RH Mechanism	\$ 50	150.00		
5	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X	150.00		
6	To Remove & Refix Radiator and Pressure Test	\$ %	150.00		
7	To Remove & Refix Front Undercarriage	\$ X	500.00		
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ X	150.00		
9	To Conduct Four Wheel Alignment	\$ 80	150.00		
10	To apply anti rust on affected parts	\$ 30	120.00		
11	To Conduct Water Leak Test	\$ X	100.00		
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 80	480.00		
	LABOUR TOTAL:	\$	5,850.00		

Stew (LKK)
12/6/24, 12.97 L

L/S

MALM

S Mys

PARTS TOTAL: \$

42,422.40

SPECIAL NETT TOTAL: \$

1,490.00

1,490.00

LABOUR TOTAL: \$

5,850.00

GRAND TOTAL: \$

\$ 49,762.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

A6A0001 / Convergence Automotive Pte Ltd NY DATE & TIME: 10/06/2024 11:39 (SGT) MITTED BY: WONG SIANG YEE RSION. 1 (10/06/2024 11:39 (SGT))



# **SINGAPORE ACCIDENT STATEMENT**

## IMPORTANT NOTICE

In Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Actual Driver.

Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any felse reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of First Submission

Reported by

**Date of Accident** 

**Exact Location of Accident** Additional Location Information

Country/State of Loss

10/06/2024 11:39 (SGT)

Both Policyholder and Actual Driver

10/06/2024 07:55 (SGT)

Singapore

ALONG WOODLANDS AVENUE 10

Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

**SNJ412B** 

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

**Email Address** 

Mobile Phone No

Alternative Phone No

No

**HUANG JIANKANG** 

SXXXX021A

TIANBAORENOVATE@gmail.com

(Phone) +65-83886038

VEHICLE PARTICULARS

Manufacturer

Model

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

CC

Lexus

Es250

TOYOTA / LEXUS ES250 4DR SEDAN (AUTO) EXECUTIVE

No - Claiming third party

Private car

Auto 2487

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Direct Asia Insurance (Singapore) Pte Ltd

MT/01369628

DRIVER

Name of Driver NRIC No

Date Of Birth Occupation

**HUANG JIANKANG** SXXXX021A 12/03/1968

Outdoor

Accident report SC1V246A0001

Page 1 of 13



Pass Date 26/09/2017 g experience 6 YEARS AND 9 MONTHS Male der Jbile Number (Phone) +65-83886038 It. Phone Number Email Address TIANBAORENOVATE@gmail.com Address APT BLK 653 WOODLANDS RING ROAD #04-470 Address complement Postcode 730653 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Side Swipe Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes

## DETAILS OF OTHER VEHICLE PROPERTY 1

Accident report SC1V246A0001

Page 2 of 13



complement
rance Company Name
fure Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Accident report SC1V246A0001

Page 3 of 13



#### BKETCHPLAN

#### IMPORTANT NOTICE

- Please report grounds the desirts of the avoident to appeal up the elema process.
   This Form must be passaded for the Delicabelles seeding the Archeol Delect.
   Internation provided must be ex justified and accusals. As a security with a more insurance component to grounds antice liability.

- A The house and exceptance of the Form by insurance companies is not an admission of policy buildy as the part of the Journace of the Form by insurance companies is not an admission of policy buildy as the part of the Journace of S. Any false responsible two the Training Police Description of Investigation.

  The report will be transmised by the Investigation the Cost Records Management Cortex established by the Connect Investigation (Investigation of the Investigation of the mode evaluate sponsible sponsible training of the Investigation of the Inve

 Consent under the Personal Data Protection Act propay
 Indentend, echnowledge, agree and concert that:
 My Insurer, my workshop and the Concert Insurance Association of Singapore ("GIA") maybe permitted to collect, see, di process my personal detaipersonal information set but in this flored and any other personal information provided by me of need by my incurer (coloribusly the "Personal Information") and disclose and transfer such Personal Information to all into vit insured valuately) involved in this accident (all insuranța) who have insured valuate(s) involved in this accident shall be ly related to so the "incursors"), the incursors' lawyers/less forms, the Monetary Authority of Gingapore and any relevant


resing, handling and/or dealing with my claims including the sold

mying out and/or dealing with my instructions or responding to any enquires by me, Emiriphesing my claims, (including the mailing of eurospondence, statements, eurosc ms of contain personal data about me to bring about delivery of the same as well as on the external co

ctively the "Purposes") Interesting who have insured vehicle(s) involved in this accedent and the insurers' lowyers/low (

monal information maylcan be disclosed by any of the Insurers and/or GIA to their third-party cornor or their languages/laws/laws), which may be stind extente of Europepers, for one or snore of the above Purpos

Actual Driver's Signature (if driver is not the policyhelder) / Date & Time



@ Accident report SC1V246A0001

Page 4 of 13



Neorthe Circumstance of the Accident
On the stuked three and dock, I was driving Vericle 14,
SNJ4128 was sidenly before B, XE41472 site supe me
from the right side, caucing my night side mirror to come
ff and damaged the pointer of tender and door.
Declaration We declare the foregoing periodicre are true in every respect.
k
Putcyholder's Signature / Data & Time Aduat Driver's Signature (if diver is not the policyholder) Wilnessed by Reporting Centre Personnel

Accident report SC1V246A0001

