

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070096/KUA3Q2**Date:** 06/09/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0005826_03
Claimant Vehicle No :	SLP5146D	Insured Vehicle No :	SNB9122X
Date of Loss:	03/07/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5146D	Engine No:	G4FGGH636432
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MJ5724998
Reg. Date:	08/06/2017 (Man. Year: 2017)	Odometer:	161503 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,585.50	5,035.50	550.00	9.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,385.00	1,310.00	75.00	5.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,970.50	6,345.50	625.00	8.97
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	6,970.50	5,050.00	1,920.50	27.55
+ GST 9.00/9.00% (S\$)	627.35	454.50	172.85	27.55
Nett Amount (S\$)	7,597.85	5,504.50	2,093.35	27.55
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,231.75		

INSPECTION

Date of Assignment:	05/07/2024		
Date Inspected:	05/07/2024	Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2024)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP5146D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER	Bent	342.00 FL	*342.00 FL
2	1		*FRONT N/S FENDER INNER SHIELD	Distorted	86.00 FL	*86.00 FL
3	1		*FRONT N/S FENDER SIDE RETAINER	Distorted	18.00 FL	*18.00 FL
4	1		*FRONT BUMPER FASCIA	Buckled	634.00 FL	*634.00 FL
5	1		*N/S TAILLAMP	Mtg Cracked	2,370.00 FL	*2,370.00 FL
6	1		*FRONT N/S SHOCK ABSORBER	Bent	283.00 FL	*283.00 FL
7	1		*FRONT N/S KNUCKLE ARM	Bent	316.00 FL	*316.00 FL
8	1		*FRONT N/S KNUCKLE BEARING HUB	Bent	135.00 FL	*135.00 FL
9	1		*FRONT N/S WHEEL BEARING	Necessary	118.00 FL	*118.00 FL
10	1		*FRONT N/S LOWER ARM	Distorted	343.00 FL	*343.00 FL
11	1		*FRONT BUMPER LOWER SPOILER	Repair	300.00 FS	*- FS
12	1		*FRONT N/S SPORT RIM	Dented	700.00 FS	*450.00 FS
13	1		*N/S SIDE MIRROR ASSY	Broken	450.00 FL	*450.00 FL
					Sub Total (S\$)	6,095.00 5,545.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	509.50 509.50
					Total Parts (S\$)	5,585.50 5,035.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	20.00	20.00
2	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	New	200.00	180.00
3	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	65.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	600.00
5	TO REMOVE,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	500.00	450.00
Gross Labour Cost (\$\$)			1,385.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >