

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07109

Vehicle Insured : SNB9122X

Accident Date : 03-Jul-2024

Date : 04-Jul-2024

Our Ref : 024130 (III) / CHAN

PAGE : 1

TEW SI KAI EDWARD
BLK 635A SENJA ROAD
#30-255
Singapore 671635

*Not Authored
11 Pgs & 5050h
Priming After Painting
5 days*

ESTIMATED COST OF REPAIR FOR KIA CERATO SLP5146D

=====

- 1 pc Front n/s fender
- 1 pc Front n/s fender inner shield
- 1 pc Front n/s fender side retainer
- 1 pc Front bumper fascia
- 1 pc N/s headlamp
- 1 pc Front n/s shock absorber
- 1 pc Front n/s knuckle arm
- 1 pc Front n/s knuckle bearing hub
- 1 pc Front n/s wheel bearing
- 1 pc Front n/s lower arm

Bu	342.00	✓
Di's	86.00	✓
Di's	18.00	✓
Bu	634.00	✓
MS CM	2,370.00	✓
Bu	283.00	✓
Ar	316.00	✓
Ar	135.00	✓
Ar	118.00	✓
Di's	343.00	✓

4,645.00

Less 10% : 464.50

- 1 pc Front bumper lower spoiler
- 1 pc Front n/s sport rim

4,180.50
R 300.00 sn X
4505N R 700.00 sn ✓

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To dismantle and lower front undercarriage

200.00 *MS*

To check and adjust wheel alignment

65.00 *601*

To putty and spray replaced parts

600.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal or fraudulent(s) is allowed
- Supplier/repairer must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SNB9122X

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

4501
500.00

Total : S\$ 6,565.50

Singapore Dollars Six Thousand Five Hundred and
Sixty Five and Cents Fifty Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SNB9122X (INDIA)

Accident Date : 03-07-2024

Date : 06-07-2024

Our Ref : 024130 / CHAN

TEW SI KAI EDWARD

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR KIA CERATO SLP5146D

1 PC N/S SIDE MIRROR ASSY

Br \$450.00 ✓
LESS 10% \$45.00
\$405.00

Singapore Dollars Four hundred Five only