

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMF 717E

	Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	SUNDRIES (SN)	NECESSARY	\$50.00	\$20.00		
1	FRONT BUMPER (SN)	DEFORMED	\$2,486.90	\$2,486.90		
1	FRONT BUMPER RETAINER LH (SN)	NOT NECESSARY	\$30.60	\$0.00		
2	FIXING DEVICE (SN)	NOT NECESSARY	\$60.40	\$0.00		
1	RETAINER PLATE FOR HEADLIGHT WASHER LH (SN)	NOT NECESSARY	\$29.90	\$0.00		
1	RETAINER PLATE FOR HEADLIGHT WASHER RH (SN)	NOT NECESSARY	\$29.90	\$0.00		
1	ADHESIVE TUBE(W536) (SN)	NECESSARY	\$552.50	\$552.50		
1	SENSOR (SN)	NOT NECESSARY	\$319.80	\$0.00		
4	SENSOR GASKET (SN)	NECESSARY	\$15.60	\$15.60		
1	GRILLE LH (SN)	NOT NECESSARY	\$166.80	\$0.00		
1	COVER TRIM GRILLE LH (SN)	NOT NECESSARY	\$63.90	\$0.00		
1	SUPPORT FRO GRILLE LH (SN)	NOT NECESSARY	\$93.40	\$0.00		
1	AIR GUIDE LH (SN)	NOT NECESSARY	\$212.00	\$0.00		
1	FRONT BUMPER SPONGE (SN)	NOT NECESSARY	\$142.10	\$0.00		
1	ADDITIONAL HEADLAMP LH (SN)	NOT NECESSARY	\$734.80	\$0.00		
		\$4,988.60	\$3,075.00			

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
TO REMOVE /REPLACE FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT		\$3,440.00	\$1,720.00		
TO RESPRAY FRONT BUMPER		\$1,600.00	\$1,400.00		
TO TRANSFER THE FRONT BUMPER SENSORS		\$500.00	\$150.00		
TO SUPPLY & INSTALL THE BODY WRAP STICKER ON AFFECTED AREAS		\$1,100.00	\$1,100.00		
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		\$250.00	\$150.00		
TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS		\$600.00	\$600.00		
		\$7,490.00	\$5,120.00		
GRAND TOTAL		\$12,478.60	\$8,195.00		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

RECOMMENDED COST OF REPAIRS \$8,195.00

Report Ref No: CS/FCI24070099/Rqp3m4

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.