

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24070103/KMA3Q2**Date:** 03/09/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100602736  
**Claimant Vehicle No :** SDY6113P **Insured Vehicle No :** SGC5739X  
 Date of Loss: 30/06/2024 Nature of Claim: TP Claim No: 4963345880SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SDY6113P**  
 Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD Engine No: L15B4428530  
 5DR (A)  
 Reg. Date: 17/11/2017 (Man. Year: 2017) Chassis No: RU11228530  
 Colour: Metallic Red Odometer: 45810 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 2,328.24          | 1,585.20          | 743.04            | 31.91         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 1,430.00          | 1,000.00          | 430.00            | 30.07         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>3,758.24</b>   | <b>2,585.20</b>   | <b>1,173.04</b>   | <b>31.21</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,050.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 3,758.24          | 2,050.00          | 1,708.24          | 45.45         |
| <b>+ GST 9.00/9.00% (S\$)</b>                   | 338.24            | 184.50            | 153.74            | 45.45         |
| <b>Nett Amount (S\$)</b>                        | <b>4,096.48</b>   | <b>2,234.50</b>   | <b>1,861.98</b>   | <b>45.45</b>  |
| <b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b> |                   | 250.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.18              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,486.68</b>   |                   |               |

**INSPECTION**

Date of Assignment: 04/07/2024  
 Date Inspected: 04/07/2024 Inspected At: Alan's United Auto Pte Ltd (HQ)  
 Blk 7 Sin Ming Industrial Estate, #01-76  
 Singapore 575642  
 Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition   | Repairer's                                                 | Amount                   |
|-----|-----|----------|----------------------------------|-------------|------------------------------------------------------------|--------------------------|
| 1   | 1   |          | *TAIL GATE                       | Bent        | 934.30 FL                                                  | *934.30 FL               |
| 2   | 1   |          | *TAIL GATE GLASS MOULDING -TOP   | Necessary   | 30.00 FL                                                   | *30.00 FL                |
| 3   | 1   |          | *TAIL GATE GLASS MOULDING -LOWER | Necessary   | 30.00 FL                                                   | *30.00 FL                |
| 4   | 2   |          | *TAIL GATE SIDE MOULDING         | Necessary   | 56.00 FL                                                   | *56.00 FL                |
| 5   | 1   |          | *TAIL GATE VEZEL EMBLEM          | Necessary   | 48.00 FL                                                   | *48.00 FL                |
| 6   | 1   |          | *REAR BUMPER FASCIA              | Dented      | 583.20 FL                                                  | *583.20 FL               |
| 7   | 1   |          | *REAR N/S BUMPER SIDE            | Serviceable | 182.30 FL                                                  | *- FL                    |
| 8   | 1   |          | *REAR N/S BUMPER REFLECTOR       | Serviceable | 189.20 FL                                                  | *- FL                    |
| 9   | 1   |          | *REAR END PANEL                  | Repair      | 407.30 FL                                                  | *- FL                    |
| 10  | 1   |          | *REAR W/S GLASS SEALANT          | Necessary   | 60.00 FS                                                   | *40.00 FS                |
| 11  | 1   |          | *SET REAR BUMPER REVERSE SENSOR  | Scratched   | 300.00 FS                                                  | *200.00 FS               |
|     |     |          |                                  |             | <b>Sub Total (\$\$)</b>                                    | <b>2,820.30 1,921.50</b> |
|     |     |          |                                  |             | <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | <b>492.06 336.30</b>     |
|     |     |          |                                  |             | <b>Total Parts (\$\$)</b>                                  | <b>2,328.24 1,585.20</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                  |          |                 |                 |
| 1                               | TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST                              | New      | 150.00          | 120.00          |
| 2                               | TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIMS BOARD AND CARPET                              | New      | 120.00          | 0.00            |
| 3                               | TO APPLY UNDERSEALING                                                                            | New      | 60.00           | 30.00           |
| 4                               | TO PUTTY AND SPRAY REPLACED PARTS                                                                | New      | 500.00          | 400.00          |
| 5                               | TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS | New      | 600.00          | 450.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                  |          | <b>1,430.00</b> | <b>1,000.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >