

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24070107/RMA3Q2
Date: 07/04/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230014371-01
Claimant Vehicle No :	SME4683Y	Insured Vehicle No :	SLU9894A
Date of Loss:	04/07/2024	Nature of Claim:	TP
		Claim No:	1380505056SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4683Y	Engine No:	G4FGJU274175
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Chassis No:	KMHD841CMJU763509
Reg. Date:	29/09/2018 (Man. Year: 2018)	Odometer:	136107 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,527.60	1,564.00	6,963.60	81.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,950.00	1,240.00	38.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,717.60	3,514.00	8,203.60	70.01
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	11,717.60	2,800.00	8,917.60	76.10
+ GST 9.00/9.00% (S\$)	1,054.58	252.00	802.58	76.10
Nett Amount (S\$)	12,772.18	3,052.00	9,720.18	76.10
+ Car Rental (6.0 x S\$100.00/day + 9.00% GST) (S\$)		654.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		3,708.18		
Global Sum Settlement (S\$)		3,700.00		

INSPECTION

Date of Assignment:	30/07/2024	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Date Inspected:	30/07/2024 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	460.00 FN	*- FN
2	10		*REAR BUMPER CLIPS	Not Necessary	49.00 FN	*- FN
3	1		*REAR BUMPER RETAINER RH	Not Necessary	45.00 FN	*- FN
4	1		*REAR FENDER RH	Repair	1,769.00 FN	*- FN
5	1		*ROCKER PANEL RH	Repair	1,800.00 FN	*- FN
6	1		*REAR DOOR RH	Bent	1,775.00 FL	*1,775.00 FL
7	1		*FRT DOOR OUTER HANDLE RH	Not Working	180.00 FL	*180.00 FL
8	2		*REAR DOOR HINGE RH	Not Necessary	64.00 FN	*- FN
9	1		*FRT DOOR RH	Repair	1,832.00 FN	*- FN
10	2		*FRT DOOR HINGE RH	Not Necessary	64.00 FN	*- FN
11	1		*REAR TYRE RIM RH	Repair	672.00 FN	*- FN
12	1		*REAR WHEEL HUB & BEARING RH	Not Necessary	454.00 FN	*- FN
13	1		*REAR TYRE 195/65 R15	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	9,444.00	1,955.00
- List Item Discount on L Items 10.00/20.00% (\$)	195.50	391.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	720.90	0.00
Total Parts (\$)	8,527.60	1,564.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	30.00	30.00
2	TO KNOCK ,WELD ,REMOVE & FIX ON ABOVE PARTS	New	1,200.00	800.00
3	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,300.00	1,000.00
4	TO REMOVE & REPLACE UNDERCARRIAGE	New	180.00	0.00
5	TO DO WHEEL ALIGNMENT	New	80.00	0.00
6	TO TRANSFER FRT & REAR DOOR	New	160.00	60.00
7	TO REMOVE & REFIX TRIMS	New	120.00	0.00
8	APPLY ANTI RUST COATING	New	120.00	60.00
Gross Labour Cost (\$\$)			3,190.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >