

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 09.07.2024
 VEH NO : SNL5714L
 MODEL : Honda Vezel
 D O A : 04.07.2024
 YR REF : GBH6535T

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SNL5714L (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Behind</i>	1	907.20 ✓
2	Rear Bumper Lower <i>3 Behind</i>	1	638.20 ✓
3	Rear Bumper Diffuser	1	304.90 ✓
4	Rear Bumper Reflector <i>new</i>	2	161.00 ✓
5	Rear Bumper Side Bracket <i>new</i>	2	310.00 ✓
6	Rear Bumper Side Retainer <i>new</i>	2	53.60 ✓
7	Reverse Sensor <i>2nd</i>	2	604.80 ✓
8	Reverse Sensor Holder <i>new</i>	4	156.80 ✓
9	Reverse Sensor Wire Harness <i>new</i>	1	463.20 ✓
10	Rear Camera <i>new</i>	1	763.20 ✓
11	Tail Lamp <i>cracked</i>	2	1,121.00 ✓
12	Tail Lamp Panel <i>new</i>	2	362.80 ✓
13	Tailgate <i>Dented</i>	1	1,288.40 ✓
14	Tailgate Spoiler <i>new</i>	1	712.10 ✓
15	Tailgate Outer Garnish <i>Behind</i>	1	801.20 ✓
16	Tailgate Side Reflector <i>cracked</i>	2	1,617.40 ✓
17	Tailgate Logo <i>crack</i>	1	58.90 ✓
18	Tailgate Emblem "Vezel" <i>new</i>	1	43.70 ✓
19	Tailgate Inner Holder <i>new</i>	1	52.00 ✓
20	Tailgate Hinges <i>2</i>	2	138.40 ✓
21	Tailgate Damper <i>new</i>	2	560.80 ✓
22	Tailgate Stopper	2	24.20 ✓
23	Tailgate Top Lock <i>2nd</i>	1	380.10 ✓
24	Tailgate Lower Lock <i>new</i>	1	39.20 ✓
25	Tailgate Inner Trim Board <i>cracked</i>	1	335.90 ✓
26	Tailgate Weatherstripe <i>ct</i>	1	211.90 ✓
27	Tailgate Windscreen Moulding <i>new</i>	1 set	149.70 ✓
28	Rear End Panel <i>Dented</i>	1	595.60 ✓
29	Rear End Panel Top Garnish <i>cracked</i>	1	186.90 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SNL5714L (HONDA VEZEL)

30	Rear End Panel Buzzer	1st New	1	85.90	x
31	Rear End Panel Antenna Sensor	changed	1	185.90	/
32	Rear Fender Inner Trim Board	Behind	2	771.20	/
33	Spare Tyre Panel	New	1	1,180.60	x
34	Spare Tyre Panel Top Cover	new	1	326.90	x
35	Utility Tray Sponge	changed	1	364.90	/
36	Rear Exhaust		1	617.20	x
37	Rear Exhaust Insulator	XHP	1	33.90	x
38	Rear Exhaust Mounting	new	1	38.90	x
39	Rear Exhaust Gasket		1 set	32.10	x

10744.60

8595.68

16,680.60

Less 20%

(3,336.12)

\$ 13,344.48

S/NETT ITEMS

1	Rear Number Plate	changed	1	\$ 30.00	/
2	Rear Number Plate Holder	cut	1	\$ 30.00	/
3	Rear Bumper Clips	New	1 set	\$ 30.00	/
4	Rear End Panel Sealant	new	1	\$ 60.00	/
5	Rear End Panel Top Garnish Clips	new	1 set	\$ 20.00	/
6	Tailgate Inner Trim Board Clips	new	1 set	\$ 30.00	/
7	Tailgate Outer Garnish Clips	new	1 set	\$ 20.00	/
8	Rear Camera	New	1	\$ 480.00	x
9	Spare Tyre Panel Insulation Pad	new	1 set	\$ 280.00	x
10	Rear Fender Inner Trim Board Clips	new	2 set	\$ 60.00	/

280

\$ 1,040.00

Total Parts

\$ 14,384.48

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,200.00	80
2	To putty & spray up paint works	\$ 1,200.00	80
3	To check wiring	\$ 50.00	30
4	To apply tuff coat	\$ 150.00	80
5	To remove and refix reverse senspr & distance setting	\$ 100.00	50
6	To remove and refix rear video recorder	\$ 100.00	50
7	To remove and refix rear camera & perform distance setting	\$ 100.00	50
8	To transfer tailgate fittings	\$ 150.00	80

RE : ESTIMATE FOR ACCIDENT REPAIR SNL5714L (HONDA VEZEL)

9	To remove & refix tailgate glass	2060	\$	180.00	120
10	To remove and refit rear exhaust pipe		\$	150.00	X
11	Towing fee		\$	60.00	X
Total Labour			\$	3,440.00	
Grand Total			\$	17,824.48	

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 10835.68
L/s: 8750
06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: