

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 08 Jul 2024

Preliminary Advice

Insured Vehicle No	: SNF2932A		
TP Vehicle No	: SLT6182X	Accident Date	: 04/07/2024
Make	: HYUNDAI ELANTRA	Assignment Date	: 05/07/2024
Date of Inspection	: 05/07/2024	Est. Duration of Repair	: 5
Inspection At	: E M SOLUTION PTE LTD (HQ) 160 SIN MING DRIVE,, #03-18, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,773.12
Revised Amount	:S\$	4,329.68
Check Items (Estimated)	:S\$	1,716.32
Total	:S\$	6,046.00
 Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.