

ASS. REC. BY:

REF:

MS6/ CS/MS624070109/Knp3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 8182X

Yr Regn:

11.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra G.C. 1591

Colour

M.L. Gold

A/C: Insured / Std / NI / NA

Sp. Reading

118006

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM11D841CMJU 369199

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

4/7/24

D.O.I.

5/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA not ready

8/7

LT Rep @ 4630k Cash (Red. \$8200.88, 63%).

07/08/24 Offer lump sum \$4,350.00 and 5 days.

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

5

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	628D
<b>Vehicle Details</b>	
Vehicle No.:	SLT6182X
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Beige
Manufacturing Year:	2017
Engine No.:	G4FGHU620895
Chassis No.:	KMHD841CMJU569199
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,960.00
Original Registration Date:	04 Nov 2017
First Registration Date:	04 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$11,960.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Nov 2027
PARF Rebate Amount:	\$7,774.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	03 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$14,278.00
<b>Total Rebate Amount:</b>	<b>\$22,052.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 04 Jul 2024

OK

\$4350  
on 07/08/2024

Not Authorized  
C1 Rng & 4654  
Recovery After Paint  
5 days

## EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: [emautosolution@singnet.com.sg](mailto:emautosolution@singnet.com.sg)

Vehicle number: SLT6182X

Vehicle Made & Model: HYUNDAI ELANTRA

Qty	List Items	Amount \$
1	Rear boot lid	1,783.60 ✓
1	Rear boot logo	58.80 ✓
1	Rear boot emblem "ELANTRA"	62.80 ✓
1	Rear boot emblem "S"	48.60 ✓
2	Rear boot lamps - L/R @ 481.60	963.20 X
1	Rear boot inner lock 116	220.60 ✓
1	Rear boot inner trim	311.50 X
1	Rear boot w/strip	nd ipis 181.20 50% in 90.60 in
2	Rear boot hinges - L/R @ 151.50	323.00 X
2	Rear boot stoppers @ 12.60	25.20 X
1	Rear bumper 495.60	cm 610.50 ✓
2	Rear bumper reflectors - L/R @ 89.50	179.00 X
1	Rear bumper difusser	383.90 ✓
1	Rear bumper reinforcement 329	481.90 ✓
2	Rear bumper side retainers - L/R @ 65.50	131.00 X
1	Rear end panel	546.80 ✓
1	Rear end panel garnish	nd ipis 181.60 ✓
1	Rear floor board	510.60 X
1	Rear floor panel	860.90 X
2	Rear fender inner trims - L/R @ 481.20	962.40 X
1	Rear smart keyless antenna	nd 182.20 ✓
2	Rear taillamps - L/R @ 664.20 389.40 n/s 7mly 0155w X	1,328.40 ✓
2	Rear taillamp panels - L/R @ 190.60	391.20 X
	Rear bumper bracket x2 488.60 X2	
		cm ✓
Sub-total		10,728.90
Less 20%		2,145.78
Total List		8,583.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Vehicle number: SLT6182X

Vehicle Made & Model: HYUNDAI ELANTRA

**Special Nett Items**

- 1 set Rear boot inner trim clip
- 1 set Rear bumper clip
- 1 set Rear no. plate
- 1 set Rear reverse sensor
- 1 Rear reverse camera

nn	50.00	X
na	50.00	✓
Net	60.00	45.00
Sharp	280.00	2.00
Net/For	580.00	3.00
Sharp		
<b>Total Special Nett</b>	<b>1,020.00</b>	

**Labour charges**

- To check rear electrical wiring
- To remove, refix rear interior trims to assist repair
- To remove, refix rear camera / sensor
- To respray undercoating
- To respray painting and etc
- Panel beating, cut, weld remove & replacing above parts

50.00	201
120.00	601
80.00	601
120.00	601
1,200.00	6001
1,600.00	6001
<b>Total Labour</b>	<b>3,170.00</b>

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,773.12**

12850.08