

Not Authorized
 11 Pm 8 46 50pm
 Recovery After Paint
 5 days

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emautosolution@singnet.com.sg

Vehicle number: SLT6182X

Vehicle Made & Model: HYUNDAI ELANTRA

Qty	List Items	Amount \$
1	Rear boot lid	RM 1,783.60 ✓
1	Rear boot logo	RM 58.80 ✓
1	Rear boot emblem "ELANTRA"	RM 62.80 ✓
1	Rear boot emblem "S"	RM 48.60 ✓
2	Rear boot lamps - L/R @ 481.60	RM 963.20 X
1	Rear boot inner lock 116	RM 220.60 ✓
1	Rear boot inner trim	RM 311.50 X
1	Rear boot w/strip	RM 181.20 50% in 90.60 in
2	Rear boot hinges - L/R @ 151.50	RM 323.00 X
2	Rear boot stoppers @ 12.60	RM 25.20 X
1	Rear bumper 495.60	CM 610.50 ✓
2	Rear bumper reflectors - L/R @ 89.50	RM 179.00 X
1	Rear bumper difusser	RM 383.90 ✓
1	Rear bumper reinforcement 329	RM 481.90 ✓
2	Rear bumper side retainers - L/R @ 65.50	RM 131.00 X
1	Rear end panel	RM 546.80 ✓
1	Rear end panel garnish	my p/s 181.60 ✓
1	Rear floor board	RM 510.60 X
1	Rear floor panel	RM 860.90 X
2	Rear fender inner trims - L/R @ 481.20	RM 962.40 X
1	Rear smart keyless antenna	RM 182.20 ✓
2	Rear taillamps - L/R @ 664.20 C389.40 n/s my CM	RM 1,328.40 ✓
2	Rear taillamp panels - L/R @ 190.60	RM 391.20 X
	Rear bumper bracket x2 @ 48.60 x2 CM ✓	
Sub-total		10,728.90
Less 20%		2,145.78
Total List		8,583.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vehicle number: SLT6182X

Vehicle Made & Model: HYUNDAI ELANTRA

Special Nett Items

1 set Rear boot inner trim clip
1 set Rear bumper clip
1 set Rear no. plate
1 set Rear reverse sensor
1 Rear reverse camera

nn	50.00	X
nn	50.00	✓
nd	60.00	45.00
Shang	280.00	200.00
nd/fer	580.00	300.00
Shang		
Total Special Nett	1,020.00	

Labour charges

To check rear electrical wiring
To remove, refix rear interior trims to assist repair
To remove, refix rear camera / sensor
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

50.00	201
120.00	601
80.00	601
120.00	601
1,200.00	6001
1,600.00	6001
Total Labour	3,170.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,773.12