



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 2024 - 68

Date: 16<sup>th</sup> August 2024

Our Ref: CS1/SCD24070110/Eqp3m4

**M/s Singapore Civil Defence Force (MHA05)**

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SBS 3747K**

**INSURED VEHICLE: XD 6103S**

**ACCIDENT DATE: 11/06/2024**

We thank you for your instruction on 03/07/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBS 3747K from M/s SBS Transit Ltd.
- b) Singapore Accident Statement and Police Report of Vehicle SBS 3747K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SBS 3747K
Make & Model	: Volvo B9TL
Chassis Number	: YV3S4P928EA165162
Year of Registration	: 2014
Engine Capacity	: 9364 cc

2. Our finding is that the repair cost of \$188.00 (before GST) quoted by M/s SBS Transit Ltd is fair & reasonable.
3. We recommend that the repairs of the entire damage require about 0.5 (Half) working days to complete.

Yours Faithfully,



CHEN TSUE YEE  
*Automotive Assessor*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SBS 3747K

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	WORKSHOP LABOUR		\$188.00	\$188.00
	CONTRACTOR'S REPAIR CHARGES (NPA)	NOT NECESSARY	\$0.00	\$0.00
			\$188.00	\$188.00
GRAND TOTAL			\$188.00	\$188.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			\$188.00
Report Ref No: CS1/SCD24070110/Eqp3m4				

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.