



5035 Ang Mo Kio Industrial Park 2 #01-373 Singapore 569538
Company UEN: 53308377W Tel: 9876 5547
Email: joyskerworks@gmail.com

ESTIMATE

TO: MS FIRST CAP
ATTENTION: MOTOR CLAIMS DEPARTMENT
SURVEY VEHICLE: YN5049H
MAKE/MODEL: MITSUBISHI CANTER
DATE OF ACCIDENT: 24-06-2024
CLAIM TYPE: THIRD PARTY CLAIM

No.	LIST ITEM	QTY	UNIT LIST PRICE (\$)	TOTAL LIST PRICE (\$)
1	FRONT HEADLAMP RH	1	\$ 501.42	\$ 501.42
2	FRONT SIGNAL LAMP RH	1	\$ 266.36	\$ 266.36
3	FRONT HEADLAMP SIDE GARNISH RH	1	\$ 230.34	\$ 230.34
4	FRONT BUMPER	1	\$ 1,010.34	\$ 1,010.34
5	FRONT BUMPER BRACKET RH	1	\$ 169.30	\$ 169.30
			SUB TOTAL	\$ 2,177.76
			LESS -25%	\$ 544.44
			TOTAL	<u>\$ 1,633.32</u>

No.	S/NETT ITEM	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR ALUMINIUM HYD LIFTER PLATFORM TAILGATE ROLLER	1	\$ 280.00	\$ 280.00
2	REAR ALUMINIUM HYD LIFTER PLATFORM TAILGATE TILT	1	\$ 2,800.00	\$ 2,800.00
3	REAR UNDER BAR	1	\$ 600.00	\$ 600.00
4	REAR UNDER BAR REFLECTIVE STICKER SET	1	\$ 150.00	\$ 150.00
				<u>\$ 3,830.00</u>

No.	LABOUR		
1	TO DISMANTLE DAMAGE TAILGATE/HYSDAULIC REPAIR	\$ 1,500.00	
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION AND POLISHING AFFECTED AREA	\$ 600.00	
3	TO DISMANTLE AND REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 600.00	
4	TO APPLY ANTI-RUST AND TUFF KOTE	\$ 120.00	
5	TO PERFROM LIGHTING AND WIRING CHECK	\$ 120.00	
6	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	
7	TO PERFROM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 250.00	

TOTAL \$ 3,270.00