

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 1527Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	* CHECK	620.00	-
2	REAR BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
1	REAR BUMPER LOWER LID	NOT NECESSARY	420.00	-
2	REAR BUMPER REFLECTOR @\$220.00	* CHECK	440.00	-
5	REAR BUMPER INNER BRACKET @\$30.00	NOT NECESSARY	150.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	420.00	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$180.50	NOT NECESSARY	361.00	-
1	REAR END PANEL	NOT NECESSARY	580.30	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	190.30	-
	LESS 20% DISCOUNT		-661.28	-
			2,645.12	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATION SEALANT (SN)	NOT NECESSARY	100.00	-
			140.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,400.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	200.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
			3,380.00	450.00
	GRAND TOTAL		6,165.12	470.00

Report Ref No. CS/INC24070117/Aqp3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		470.00
(REPAIR COST NOT CONCLUDE)		
(EXCLUDE CHECK ITEMS S\$848.00 NETT)		

Report Ref No. CS/INC24070117/Aqp3m4(N)

TOTAL FOR SPARE PARTS: \$ 2,785.12 \$ 20.00 TOTAL FOR LABOUR: \$ 3,380.00 \$ 450.00 TOTAL REPAIR COST: \$ 6,165.12 \$ 470.00

XXX.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.