

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0237/24
DATE : 02-JUL-2024

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
S(068909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S J & KOH AIR-CONDITIONING SERVICES
ADDRESS : 365 CORPORATION DRIVE
#03-407
S(610365)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : D24MTPCVE001470
VEHICLE NO : GBF732R
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25392104A
CHASSIS NO : JN1MC2E26Z0006278
MILEAGE : 176437 KM
DATE IN : 02/07/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER - 9645 0084 elmer@fanchong.com
ACCIDENT DATE : 01/07/2024

Not Authorized
LKH
means
8/7/24 @ 10.30am
take ph. After up
3 days
2/2 \$1623

LRK is to Consenting hence no by
the prior of the following:
• To rectify before/after spray painting
• To display damaged parts in a survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBF732R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW FRT BUMPER AND FRT RH DOOR FRT RH SIDE STEP	1720.00	860
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1400.00	700
3	ZZ/003	APPLY SEALANT TO FRT RH DOOR	100.00	X
4	ZZ/004	REMOVE AND TRANSFER FRT RH DOOR MECHANISM	120.00	X
5	ZZ/005	SUPPLY FRT RH DOOR LTA STICKER	15.00	✓
6	ZZ/006	CHECK AND INSPECT RH HEADLAMP, REPLACE IF DAMAGE	48.00	✓
TOTAL LABOUR CHARGES			3403.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF732R

DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1 FRT RH SIDE STEP	96150-3XA0A	53.40	X	
2 SUNDRIES	NPN			117 50.00 X
3 FRT RH DOOR	H010M-3XAMB	1191.80	X	
4 RH SIDE BRACKET FRT BUMPER	62220-3XA0B	183.30	X	
5 FRT BUMEPB	62022-3XA0H	636.80	X	
SUB TOTAL		2065.30	0.00	50.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		413.06	0.00	0.00
GRAND TOTAL		1652.24	0.00	50.00
OVERALL TOTAL		1702.24		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBF732R

TOTAL LABOUR CHARGES	3403.00
TOTAL SPARE PARTS CHARGES	1702.24

GRAND TOTAL	5105.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.