



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070125/Tvh3e2
16 RAFFLES QUAY	Date:	05/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4722T	Veh. Inspected	SMD 850M
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005904MFCT	Excess	\$0.00
Assign From	BETTY WONG	Assign Date	05/07/2024

2. Vehicle Details

Make & Model	KIA CARENS	C.C	1685
Engine No.	D4FDJD025971	Year of Reg.	31/07/2018
Chassis No.	KNAHU815VJ7211654	Colour	BLUE
Odometer	470138 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R16	GREENTRAC	6
L/H Front Tyre	205/55 R16	GREENTRAC	6
R/H Rear Tyre	205/55 R16	GREENTRAC	6
L/H Rear Tyre	205/55 R16	GREENTRAC	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/07/2024	Inspection Date	08/07/2024
Survey held at	60 JALAN LAM HUAT, LEVEL 7, #07-43 SINGAPORE 737869 - REPAIRER: PREMIER AUTOMOTIVE SERVICES PL		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days