

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

not Authorised
19/6/24

L/S \$5000 /
vehicle. Advise -
5 days.

Vehicle number: SMP691S

Vehicle Made & Model: HONDA SHUTTLE

Qty	List Items	Amount \$
1	Front door <i>ALL</i>	<i>Body DO</i> 1,265.60 ✓
1	Front door glass outer moulding <i>11</i>	181.20 X
1	Front door glass run channel <i>11</i>	241.50 X
1	Front door glass regulator assy <i>11</i>	481.60 X
1	Front door inner lock <i>Daye</i>	360.50 ✓
1	Front door insulation <i>11</i>	130.20 X
1	Front door trim board <i>11</i>	781.30 X
1	Front door w/strip <i>RM</i>	182.90 ✓
1	Front fender - LH <i>R</i>	580.60 X
1	Front fender emblem <i>RM</i>	68.60 ✓
1	Front fender inner shield <i>11</i>	142.60 X
1	Centre pillar - LH <i>R</i>	865.90 X
1	Side sill panel garnish <i>To. n</i>	631.60 ✓
1	Side sill panel - LH <i>DO Bent</i>	1,055.90 ✓
1	Rear door - LH <i>Body DO</i>	1,265.60 ✓
1	Rear door glass outer moulding <i>11</i>	161.90 X
1	Rear door glass run channel <i>11</i>	211.50 X
1	Rear door glass regulator assy <i>11</i>	461.30 X
1	Rear door insulation <i>11</i>	130.20 X
1	Rear door checker <i>11</i>	81.50 X
2	Rear door hinges @ 68.60 <i>SM</i>	137.20 X
1	Rear door w/strip <i>RM</i>	182.60 ✓
1	Rear fender - LH <i>R</i>	991.50 X
1	Rear bumper <i>R</i>	1,210.50 X
Sub-total		11,803.80
Less 20%		2,360.76
Total List		9,443.04

Vehicle number: SMP691S

Vehicle Made & Model: HONDA SHUTTLE

Special Nett Items

1 set	F/R	door black tape @ 120	nee	240.00	100
1 set	F/R	wheel hub cap	Ree one	280.00	120
1 set	Side	sill panel ganish clip	nee	80.00	30
Total Special Nett				600.00	

Labour charges

To check front & rear electrical wiring	80.00	20
To respray undercoating	100.00	80
To respray painting and etc	1,200.00	1100
Panel beating, cut, weld remove & replacing above parts	1,500.00	800
Total Labour	2,880.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,923.04

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after repair work
- To display damaged parts in a prominent place
- Parts prices are subject to confirm with
- The survey is on a "Without Paint" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-approved
- Is subject to final approval from the Repairer

Acknowledged by Repairer:
Signature: _____
Date: _____

P- 5013-3
202
6010-64
250
2000
6260-64
202
5008.