

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay

#21-00

Singapore 048580

Tel: 62222311

Fax: 62223547

Attn: Motor Claim Department

Your Ref No: TP 0724-8114

Claim Type: Third Party

Accident Date: 04 July 2024

TP Veh Reg No: SMB177J

Estimate No: **EST1511478**

Date: 04 Jul 2024

Policy No: MT/01136666/01

Veh Reg No: SJV5826S

Make/Model: KIA CERATO FORTE 1.6
AT SX ABS D/AB 2WD
4DR

Chassis No: KNAFW411MA5122015

Engine No: G4FC9H290458

Reg. Date: 29 Jan 2010

*NOT Authorized
Morris
15/7/24
1/5 # 2500
Tel: 9611111
4 days*

Estimate Repair Cost to Vehicle No: **SJV5826S**

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER <i>cur/70.1</i>	548.00	1 PC	548.00	—
2 REAR BUMPER SIDE RETAINER - LH/RH <i>o/scre n/s n</i>	28.00	2 PC	56.00	<i>120</i>
3 REAR BUMPER CLIPS <i>new</i>	4.90	10 PC	49.00	—
4 REAR BUMPER LOWER GARNISH (BLACK) <i>70.1</i>	105.00	1 PC	105.00	—
5 REAR BUMPER FOAM <i>11</i>	141.00	1 PC	141.00	<i>q</i>
6 REAR BUMPER REINFORCEMENT <i>11</i>	305.00	1 PC	305.00	<i>q</i>
7 TAILLAMP - RH <i>320</i>	198.00	1 PC	198.00	—
8 TAILLAMP CLIPS - RH <i>11</i>	8.00	2 PC	16.00	<i>x</i>
9 REAR FENDER - RH <i>57/300</i>	985.00	1 PC	985.00	—
10 REAR FENDER COWLING - RH <i>11</i>	23.00	1 PC	23.00	<i>x</i>
11 REAR FENDER COWLING CLIPS - RH <i>11</i>	4.90	10 PC	49.00	<i>x</i>
12 REAR GLASS MOULDING <i>11</i>	66.00	1 PC	66.00	<i>x</i>
13 REAR BOOT LAMP - RH <i>11</i>	150.00	1 PC	150.00	<i>x</i>
			2,691.00	
		Less 10%	-269.10	2,421.90
Special Net				
14 REAR BUMPER SENSOR (4PC SET) <i>su</i>	300.00	1 PC	300.00	<i>x</i>
15 REAR BUMPER STICKER <i>nu</i>	200.00	1 PC	200.00	<i>120</i>
16 SEALANT <i>11</i>	20.00	2 PC	40.00	<i>x</i>
17 SPONGE TAPE <i>11</i>	20.00	1 PC	20.00	<i>x</i>
				560.00
Labour				
18 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	900.00	1 JOB	900.00	<i>600</i>
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	650.00	1 JOB	650.00	<i>600</i>
20 TO CHECK WIRING-	30.00	1 JOB	30.00	<i>20</i>
21 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00	<i>60</i>
22 TO TRANSFER REAR BUMPER SENSOR-	80.00	1 JOB	80.00	<i>30</i>
23 TO TUFFKOTE-	60.00	1 JOB	60.00	<i>30</i>
24 TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	<i>x</i>
			1,750.00	2,020.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	5,001.90
Add GST @ 9%	450.17
Total Amount Payable SGD	5,452.07

SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED FIFTY TWO AND CENTS SEVEN ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1913
102
1771.70
120
1340
3191.70
2545

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE