

WE GARAGE

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile: +65 9009 6622

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5 Jul 2024

Vehicle No: **SGM79Y**

Model: **TOYOTA CAMRY**

not Authorized
in
8/7/24
2/c \$1500
Take photo After 1st
3 days.

QTY

DESCRIPTION

List Items

1	Rear Bumper	CU 7/7orn	\$	768.40	/
2	Rear Bumper Side Retainers R/L	^n	\$	137.40	X
1	Rear Fender (L)	R	\$	1,368.70	X
1	Rear Fender Inner Shield	^^	\$	176.20	X
1	Rear Fender Air Gate	^^	\$	81.50	X
1	Rear Windscreen Moulding	^^	\$	121.90	X
1	Rear Taillamp (L)	^^	\$	641.70	X
			\$	3,295.80	
			Less 25%	\$	823.95
			\$	2,471.85	

Special Nett Items

1	1 Set Rear Bumper Clips	nu	\$	65.00	30 s/n
1	1 Set Rear Bumper Clips	Repeals	\$	65.00	X
1	Rear Tyre	SVL	\$	250.00	X
1	Rear Rim (LH)	CU 7	\$	800.00	500 s/n
			\$	1,180.00	

Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	20
1	To remove and refit rear windscreen gladd	^^	\$	180.00	X
1	To apply undercoating.	^^	\$	120.00	X
1	Panel beating.		\$	1,000.00	300
1	To re-spray painting on the affected areas.		\$	1,200.00	400
1	To conduct wheel alignment		\$	150.00	60
			\$	2,730.00	

Grand Total: \$ 6,381.85