



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24070128/Tvh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583	Date:	16/12/2024
	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 3645H	Veh. Inspected	SNM 8604X
Policy No.	-	Coverage	0
Claim No.	IVS24/1295	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	05/07/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA	C.C	1490
Engine No.	M15AY686138	Year of Reg.	27/10/2023
Chassis No.	MXPL101056219	Colour	WHITE
Odometer	57317 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	DUNLOP	6
L/H Front Tyre	185/65R15	DUNLOP	6
R/H Rear Tyre	185/65R15	DUNLOP	6
L/H Rear Tyre	185/65R15	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspection Date	09/07/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days