

**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**





**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**



**PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X**





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 23 of 23)

PHOTOGRAPHS FOR VEHICLE NO. : SNM 8604X

