

ASS. REC. BY: Taujiah

REF: CS/LIP24070128/Tvh3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SMK 3645H
 Policy No. _____
 Claims No. IVS24/1295
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
	<input checked="" type="checkbox"/>

Bal. or Market Value: \$155K
 IDAC Accident Rport _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNM 8604X Yr Regn: 2023 out
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Sienta c.c. 1490
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 57317 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MXPL10056219
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NII / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/65R15
 R: _____
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 2/7/2024 D.O.I. 9/7/24
 Survey held at Thiam Heng Huat
 Des. of Damages: Frt Rear / O/S / N/S / U/G / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/12/24	LS \$5300 confirmed by whatsapp (Red 10,421.73, 66%)

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: 6
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 1) _____
 2) _____
 Rep. Format: _____
 Lump Sum / L.B.L. (\$) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
\$ + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA SIENTA

Date: 10/07/2024

Engine/Chassis No.: MXPL101056219

Claim Type: TP

Date of accident: 02.07.24

VRN: SNM8604X

Damaged area: Rear

List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tailgate	1	\$ 2,350.00	\$ 2,350.00	bt ✓
2	Tailgate outer moulding	1	\$ 385.00	\$ 385.00	Xun ✓
3	Tailgate logo	1	\$ 72.20	\$ 72.20	rec ✓
4	Tailgate weatherstrip	1	\$ 372.30	\$ 372.30	twi ✓
5	Tailgate hybrid emblem	1	\$ 83.00	\$ 83.00	rec ✓
6	Antenna buzzer	1	\$ 269.00	\$ 269.00	eng ✓
7	Tailgate hinge	2	\$ 135.00	\$ 270.00	Xun ✓
8	Tailgate damper	2	\$ 177.00	\$ 354.00	Xun ✓
9	Tailgate windscreen moulding	1	\$ 194.00	\$ 194.00	rec ✓
10	Taillamp	2	\$ 789.00	\$ 1,578.00	Xun ✓
11	Rear bumper side reflector	2	\$ 177.00	\$ 354.00	RHXun LHcut ✓
12	Tailgate inner trim	1	\$ 297.00	\$ 297.00	de ✓
13	Rear wheel house n/s	1	\$ 994.00	\$ 994.00	X
14	Rear bumper sensor holder	4	\$ 27.00	\$ 108.00	?
15	Rear bumper	1	\$ 1,150.00	\$ 1,150.00	de ✓
16	Rear bumper retainer	2	\$ 76.00	\$ 152.00	RHXun LHde ✓
17	Rear bumper bracket	2	\$ 68.00	\$ 136.00	RHXun LHde ✓
18	End panel	1	\$ 785.00	\$ 785.00	bt ✓
19	End panel top garnish	1	\$ 284.00	\$ 284.00	de ✓
20	Rear fender inner trim n/s	1	\$ 778.40	\$ 778.40	de ✓
21	Rear licence plate lamp	2	\$ 113.90	\$ 227.80	Xun ✓
22	Tailgate inner handle	1	\$ 86.30	\$ 86.30	Xun ✓
23	Taillamp lower bracket	2	\$ 49.00	\$ 98.00	Xun ✓
24	Tailgate lock	1	\$ 456.40	\$ 456.40	bt ✓
25	Spare tyre panel top board	1	\$ 443.90	\$ 443.90	de ✓
26	Spare tyre panel	1	\$ 884.00	\$ 884.00	X
Subtotal				\$ 13,162.30	
List discount				25.00%	
Total				\$ 9,871.73	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tailgate windscreen inner seal	1	\$ 100.00	\$ 100.00	rec/50 ✓
2	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00	rec/60 ✓
3	Tailgate outer garnish clips	6	\$ 5.50	\$ 33.00	Xun ✓
4	Spare tyre panel sealant	1	\$ 100.00	\$ 100.00	Xun ✓

Repair Estimate

5	Tailgate inner trim clips	10	\$ 5.50	\$ 55.00	20nel ✓
6	Taillamp clips	6	\$ 5.50	\$ 33.00	Xnn
7	End panel top garnish clips	6	\$ 5.50	\$ 33.00	20nel ✓
8	End panel sealant	1	\$ 100.00	\$ 100.00	40nel ✓
9	Rear licence plate & frame	1	\$ 55.00	\$ 55.00	bf/45
10	Reverse sensor	4	\$ 280.00	\$ 1,120.00	?
11	Rear bumper clips	12	\$ 5.50	\$ 66.00	40nel ✓
12	Rear wheel house sealant n/s	1	\$ 100.00	\$ 100.00	Xnn
13	Rear licence plate & frame	1	\$ 55.00	\$ 55.00	Xnn
14	Sundries	1	\$ 50.00	\$ 50.00	Xnn
				Total	\$ 2,000.00

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	9	\$ 1,800.00	700
2	To disconnect wire harnesses of electrical components to facilitate repairs, reconnect and check functions.	0.5	\$ 100.00	40
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	60
4	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	120
5	Supply spray paint material and necessary items to affected area / panel.	8	\$ 1,600.00	700
6	To rust proof all affected portions after repair.	0.5	\$ 100.00	40
			Total labour	\$ 3,850.00

Estimate Grand Total	\$ 15,721.73
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
wp' 9/7/24
L/S Resurvey after repair
6-7 days
taufik@lkkauto.com