

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200907227R

CLASSIC ALUMINIUM INDUSTRY PTE. LTD.
BLK 3018 BEDOK NORTH STREET 5
03-26
SINGAPORE 486132
TEL : 6448 8314 FAX :
PH : 9108 7865 JOSLIN
ATTN :

ESTIMATE BILL

Number : EB00006542
Date : 05/07/2024
Case No : AD00014876
Vehicle No : GBH9794S
Chassis: JTFAT35Y30K211829
Year of Mfr 2018
Policy No 23-MS011095-R04
Model : TOYOTA DYNA

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE	1.0	1,673.10	25	1,254.83
2	TAILGATE LOGO - DYNA	1.0	28.50	25	21.38
List Price - Parts Sub Total					1,276.21
3	TAILGATE LOGO - 70KM/H	1.0	30.00	0	30.00
4	TAILGATE COMPANY LOGO	1.0	350.00	0	350.00
5	TAILGATE END PANEL - REPAIR	1.0			
Special Nett Price - Parts Sub Total					380.00
Parts Total					1,656.21
6	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
7	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
8	ANTI-RUST COATING	1.0	50.00	0	50.00
Labour 1 Sub Total					1,250.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) before resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : THREE THOUSAND ONE HUNDRED SIXTY-SEVEN AND CENTS SEVENTY-SEVEN ONLY			Less Excess		0.00
			SUBTOTAL		2,906.21
			GST 9.00%		261.56
			TOTAL		3,167.77

Date of accident : 03/07/2024 08:56 AM. Place : UPPER CHANGI ROAD EAST

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE