



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJD 3833D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$1,772.00	\$0.00
1	REAR BUMPER RETAINER RHS	SERVICEABLE	\$133.14	\$0.00
	LESS 20.00% DISCOUNT		(\$381.03)	\$0.00
			\$1,524.11	\$0.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR BUMPER STICKER WRAP (SN)	NECESSARY	\$800.00	\$650.00
			\$850.00	\$700.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEAT-ACCIDENT AREA,REMOVE AND REFIT REAR BUMPER. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		\$600.00	\$120.00
	SPRAY PAINT-REAR BUMPER,REAR FENDER		\$600.00	\$0.00
	CHECK WIRING AND CHECK ALIGNMENT		\$80.00	\$0.00
			\$1,280.00	\$120.00
GRAND TOTAL			\$3,654.11	\$820.00
RECOMMENDED COST OF REPAIRS				\$820.00
Report Ref No: CS/AGI24070131/Knp3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.