

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 2440 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID. S/N \$	480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE. S/N \$	400.00 /	
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM AND REGAS AND PRESSURISE COOLING SYSTEM. S/N \$	1,600.00 /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	5,600.00 / 2,500 3000	
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER \$	3,700.00 / 2200	
6	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	292.00 /	
SUB - TOTAL LABOUR CHARGES		: \$ 12,072.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 2440 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de /</i>	1	\$ 2,736.00	
2	FRONT BUMPER FIXING PARTS <i>an /</i>	1	\$ 209.00	
3	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 49.00	
4	FRONT BUMPER GRILLE CENTER <i>an /</i>	1	\$ 201.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 645.00	
6	FRONT BUMPER CLOSING ELEMENT - LH <i>?</i>	1	\$ 357.00	
7	FRONT BUMPER COVER TRIM - LH <i>mis /</i>	1	\$ 204.00	
8	FRONT ADAPTER WHEEL HOUSING LINER - LH <i>?</i>	1	\$ 48.00	
9	RADIATOR GRILLE <i>an /</i>	1	\$ 1,784.00	
10	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	1	\$ 235.00	
11	STICKER FOR AIR CONDITIONER <i>an /</i>	1	\$ 10.00	
12	SIGN CAUTION STICKER <i>an /</i>	1	\$ 25.00	
13	FRONT AIR GUIDE GRILLE - LH <i>mis /</i>	1	\$ 235.00	
14	FRONT BUMPER COVER <i>?</i>	1	\$ 153.00	
15	FRONT FOAM FILLER PIECE <i>?</i>	1	\$ 237.00	
16	FRONT REINFORCEMENT BEAM <i>?</i>	1	\$ 1,055.00	
17	FRONT BRACKET <i>?</i>	1	\$ 30.00	
18	LED HEALDIGHT - LH <i>bro /</i>	1	\$ 6,647.00	
19	LED HEADLIGHT POWER MODULE - LH <i>?</i>	1	\$ 904.00	
20	LED HEADLIGHT CONTROL UNIT <i>?</i>	1	\$ 664.00	
SUB TOTAL SPARE PARTS			\$ 16,428.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 2440 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LED HEADLIGHT LIFT CYLINDER - LH ?	1	\$ 170.00	
22	LED HEADLIGHT HOSE - LH ?	1	\$ 86.00	
23	WASH WATER RESERVOIR de-	1	\$ 238.00	
24	FRONT WINDSCREEN WASHER PUMP ?	1	\$ 147.00	
25	SEAL ?	1	\$ 4.00	
26	STRAINER ?	1	\$ 26.00	
27	END CAP ?	1	\$ 26.00	
28	BONNET b7-	1	\$ 3,392.00	
29	BONNET ATTACHMENT PARTS X	1	\$ 184.00	
30	BONNET LID HINGE - LH / RH X	2	\$ 150.00	
31	BONNET STOP BUFFER an /	2	\$ 16.00	
32	BONNET LOCK LATCH X	1	\$ 116.00	
33	BONNET STRICKER - LH / RH X	2	\$ 274.00	
34	BONNET EDGE PROTECTION re /	1	\$ 35.00	
35	BONNET HOOK X	1	\$ 79.00	
36	BONNET LID LOCK MICRO SWITCH X	2	\$ 491.00	
37	BONNET BOWDEN CABLE - CENTER X	1	\$ 71.00	
38	BONNET LID LOCK COVER X	1	\$ 12.00	
39	BONNET SOUND ABSORBER X	1	\$ 275.00	
40	PLENUM CHAMBER COVER sca /	1	\$ 296.00	
SUB - TOTAL SPARE PARTS		:	\$ 6,088.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 2440 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WHEEL HOUSING LINER - LH <i>cm</i>	1	\$	204.00
42	FRONT WHEEL HOUSING LINER ATTACHME PARTS - LH <i>cm</i>	1	\$	105.00
43	RADIATOR AIR GUIDE - LH ?	1	\$	59.00
44	RADIATOR AIR GUIDE - RH ?	1	\$	86.00
45	RADIATOR SEAL - RH OUTER ?	1	\$	10.00
46	RADIATOR AIR GUIDE - UPPER CENTER ?	1	\$	21.00
47	FRONT LOCK CARRIER <i>cm</i>	1	\$	908.00
48	RADIATOR COLLANT 1.0 LTR <i>cm</i>	6	\$	332.00
49	A/C CONDENDER ?	1	\$	846.00
50	ADDITIONAL RADIATOR ?	1	\$	987.00
51	RADIATOR ?	1	\$	1,177.00
52	BRACKET ?	2	\$	94.00
53	SEAL RING ?	1	\$	16.00
54	SEAL RING ?	1	\$	15.00
55	FRONT PARKING AID - INNER/OUTER ?	1	\$	572.00
56	FRONT PARKING AID SEAL RING <i>cm</i>	4	\$	11.00
57	FRONT NO. PLATE <i>cm</i>	S/N	\$	60.00
58	SUNDRIES ?		\$	1,000.00
TOTAL SPARE PARTS			:	\$ 29,019.00
TOTAL LABOUR CHARGES			:	\$ 12,072.00
GRAND TOTAL			:	\$ 41,091.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Psm - Hp 9001068*
: *08/07/24*
: *10 days*
: *EXCESS: TBA*
: *Repair*
: *Res by paint*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT