



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

8 July 2024

REG NO.: SNP 1233 M
MAKE/MODEL: BMW 318

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear boot lid R	\$ 1,990.00 X
2	Rear boot hinges 11	\$ 450.00 X
2	Rear boot lamps 11	\$ 780.00 X
1	Rear boot lock 11	\$ 272.50 X
1	Rear boot logo SW	\$ 79.00 X
1	Rear boot rubber 11	\$ 225.00 X
2	Rear taillamps 11	\$ 1,310.00 X
1	Rear end panel R	\$ 1,018.50 X
1	Rear end panel inner garnish 11	\$ 289.00 X
1	Rear bumper Dis	\$ 1,790.00
2	Rear bumper brackets 11	\$ 98.00 X
1	Rear bumper centre lower moulding CR	\$ 188.10
1	Rear bumper inner frame garnish CR	\$ 335.00
1	Rear bumper lower diffuser 11	\$ 485.00 X
2	Rear bumper reflectors 11	\$ 230.00 X
1	Rear bumper reinforcement Bent	\$ 685.00
2	Rear bumper side brackets 11	\$ 190.00 X
2	Rear bumper side retainers 11	\$ 279.90 X
4	Rear bumper PDC sensors SW	\$ 1,254.00 X
1	Control module for park assistant kit Doyle	\$ 345.00
1	Control unit for smart opener Repub	\$ 365.00 X
1	Rear exhaust silencer 11	\$ 1,980.00 X
2	Rear exhaust mountings 11	\$ 90.00 X
		\$ 14,729.00
Less 5%		\$ 736.45
		\$ 13,992.55

<u>SPECIAL NETT ITEMS</u>		
1	Rear bumper clip (1 set) 11	\$ 50.00 30
		\$ 50.00

<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 120.00 X
3	To remove and refit rear reverse sensor.	\$ 150.00 30
4	To transfer boot lid mechanism and wiring assembly.	\$ 80.00 X
5	To remove, refit and replace exhaust silencer and mountings.	\$ 150.00 X
6	To apply undercoating.	\$ 180.00 X
7	Panel beating.	\$ 1,600.00 420
8	To re-spray painting on the affected areas.	\$ 1,500.00 500
		\$ 3,860.00

GRAND TOTAL :

\$ 17,902.55

P. 2764.1
52
2625.90
30
970
3625.90