



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department \ Motor Claim

Your Ref No: -
Claim Type: Third Party
Accident Date: 28/06/2024
TP Veh Reg No: SHC4950X

Estimate No: ES2400065

Date: 04 Jul 2024

Policy No:

Veh Reg No: SKR4144S

Make/Model: MERCEDES BEN C180
AVANTGARDE (R17
LED)

Chassis No: WDD2050402R007831

Engine No: 27491030211478

Reg. Date: 06/02/2015

Estimate Repair Cost to Vehicle No :SKR4144S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT TYRE - RH	400.00	1 PC	400.00	X
2 FRONT WHEEL RIM - RH	1,450.20	1 PC	1,450.20	X
			1,850.20	1,850.20
Spare Parts				
3 FRONT BUMPER	2,145.00	1 PC	2,145.00	X
4 FRONT BUMPER SIDE RETAINER - LH	142.20	1 PC	142.20	X
5 FRONT BUMPER SIDE RETAINER - RH	142.20	1 PC	142.20	X
6 FRONT BUMPER CLIPS	100.00	1 SET	100.00	X
7 FOG LAMP GARNISH - RH	398.50	1 PC	398.50	X
8 HEAD LAMP - RH	5,685.70	1 PC	5,685.70	X
9 FRONT FENDER - RH	1,182.60	1 PC	1,182.60	X
10 FRONT FENDER INNER SHIELD	265.70	1 PC	265.70	X
11 FRONT BUMPER INNER SHIELD CLIP	80.00	1 PC	80.00	X
			10,141.90	10,141.90
Labour				
12 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	2001
13 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	4001
14 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	220.00	1 JOB	220.00	X
15 WHEEL ALIGNMENT	260.00	1 T	260.00	X
16 TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	151
			2,630.00	2,630.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer,

Signature:

Date: