

ZOOM AUTOWERKS PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- ~~Third party survey is not allowed~~ "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

8 July 2024

Not Authorized
in
moral

8/7/24

6 days $2 \leq 8$ $\frac{4100}{\text{Uneph. Hb-119}}$

REG NO.: SLD 5221 H

MAKE/MODEL: TOYOTA VIOS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear boot lid	\$ 2/201 781.70 ✓
2	Rear boot hinges	\$ 11 129.80 X
1	Rear boot inner lock	\$ 121 145.60 ✓
1	Rear boot outer garnish	\$ 11 269.50 X
1	Rear boot logo	\$ 11 48.50 ✓
1	Rear boot weatherstrip	\$ 101 181.20 ✓
1	Rear boot "VIOS" emblem	\$ 11 42.90 ✓
1	Rear boot "E" emblem	\$ 11 38.90 ✓
2	Rear taillamps	\$ 11 671.80 ✓
1	Rear end panel	\$ 101 775.90 ✓
1	Rear end panel inner garnish	\$ 11 211.10 ✓
1	Rear bumper	\$ 11 685.50 ✓
1	Rear floor panel tools storage 1/5	\$ 101 171.00 ✓
1	Rear floor panel top board	\$ 101 191.80 ✓
1	Rear bumper reflector 1/5	\$ 11 92.90 ✓
1	Rear bumper reinforcement	\$ 11 412.00 ✓
2	Rear bumper side retainers	\$ 11 97.30 X
		\$ 4,947.40
	Less 25%	\$ 1,236.85
		\$ 3,710.55

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$	50.00	50
1	Rear reverse sensor (1 set)	\$	350.00	X
		\$	400.00	

S/N	LABOUR CHARGES
-----	----------------

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes. <i>upholstery</i>	\$	150.00	60
3	To remove and refit rear reverse sensor.	\$	120.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$	80.00	50
5	To apply undercoating.	\$	180.00	60
6	Panel beating.	\$	1,500.00	650
7	To re-spray painting on the affected areas.	\$	1,400.00	900
		\$	<u>3,510.00</u>	

GRAND TOTAL :

\$ 7,620.55

$$\begin{array}{r} P-4450.60 \\ 252 \\ \hline 3338.10 \\ 30 \\ 1770 \\ \hline 5138.1 \\ 4110. \end{array}$$