



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0531/2024/KS
DATE : 8-Jul-24
WIP : 22477

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME ADDRESS

: MS LILIAN CHEW GAIK LOOI
: 590 YIO CHU KANG ROAD
: #02-01

TELEPHONE TYPE OF CLAIM

: SINGAPORE 787073
: HP +65 98529635

POLICY NO VEHICLE NO

: OWN DAMAGE CLAIM
: 2100425458-08
: SKU 8419 H

MODEL CODE

: A4 1.8T FSI MU 8K203

MODEL YEAR

: 19/8/2015

ENGINE NO

: CJE 102530

CHASSIS NO

: WAUZZZ8KFA128476

MILEAGE

: KM

DATE IN

:

ESTIMATED BY

: JOHNNY BOO / ALLAN WU

ACCIDENT DATE

: 7-Jul-24

PLACE OF ACCIDENT

: CARPARK THOMSON GROVE CONDO



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 8419 H.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$ 360.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 / 250 /	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 / 1500 /	
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 2,600.00 / 1650 + 200 = 1850 /	
5	1U RENEW RHS FKUN I KIM. 1U CARRY OUT WHEEL ALIGNMENT	S/N \$ 280.00 /	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00 /	
TOTAL LABOUR CHARGES		: \$ <u><u>6,682.00</u></u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 8419 H.

DAMAGED PARTS & PRICES				REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT	
1	FRONT BUMPER <i>Scu</i>	1	\$ 3,061.00	2488 2448
2	FRONT BUMPER FIXING PARTS <i>Xm</i>	1	\$ 286.00	
3	FRONT BUMPER SECURING STRIP - RH <i>?Xm</i>	1	\$ 45.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?Xm</i>	1	\$ 286.00	
5	FRONT BUMPER GUIDE FRAME - RH <i>?Xm</i>	1	\$ 103.00	
6	FRONT BUMPER VENT GRILLE- RH <i>?Xm</i>	1	\$ 169.00	
7	FRONT HALOGEN FOG LAMP - RH <i>Xm</i>	1	TBC	
8	FRONT BUMPER GUIDE SECTION - RH <i>?Xm</i>	1	\$ 46.00	
9	HEADLIGHT - RH <i>Scu</i>	1	\$ 2,646.00	2116.80
10	HEADLIGHT CONTROL UNIT - RH <i>?Xm</i>	1	\$ 1,423.00	
11	HEADLIGHT POWER MODULE - RH <i>?Xm</i>	1	\$ 762.00	117.60
12	HEADLIGHT MOUNTING - RH <i>?Xm</i>	1	\$ 147.00	
13	LIFT CYLINDER - RH <i>Xm</i>	1	\$ 252.00	
14	LIFT CYLINDER HOSE <i>Xm</i>	1	\$ 233.00	
15	FRONT FENDER - RH <i>St</i>	1	\$ 1,185.00	948.00
16	FRONT FENDER ATTACHMENT PARTS - RH <i>Xm</i>	1	\$ 67.00	
17	FRONT FENDER BRACKET - RH <i>Scu</i>	1	\$ 64.00	51.12
18	FRONT FENDER BRACE - RH LOWER <i>Scu</i>	1	\$ 177.00	141.20
19	FRONT FENDER CLOSING ELEMENT - RH <i>Scu</i>	1	\$ 160.00	
20	FRONT FENDER SEAL - RH <i>Xm</i>	1	\$ 38.00	
SUB TOTAL SPARE PARTS			\$ 11,150.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6368 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 8419 H.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - RH <i>2 X n</i>	1	\$ 289.00	
22	WHEEL HOUSING LINER ATTACHMENT PARTS - RH <i>X n</i>	1	\$ 50.00	
23	BONNET <i>X n</i>	1	\$ 3,459.00	
24	BONNET ATTACHMENT PARTS <i>X n</i>	1	\$ 184.00	
25	BONNET HINGE - LH / RH <i>X n</i>	2	\$ 182.00	
26	BONNET CATCH HOOK <i>X n</i>	1	\$ 174.00	
27	BONNET EDGE PROTECTION <i>X n</i>	1	\$ 35.00	
28	FRONT ALUMINIUM RIM - RH <i>2 X n</i>	1	\$ 1,565.00	
29	FRONT ALUMINIUM RIM RUBBER VALVE - RH <i>X n</i>	1	\$ 5.00	
30	SUNDRIES <i>2 new</i>	\$	\$ 500.00	<i>60.16</i>
TOTAL SPARE PARTS			: \$ 17,254.00	
TOTAL LABOUR CHARGES			: \$ 6,682.00	
GRAND TOTAL			: \$ 23,936.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rame - Hp 900WV6
: 09/07/24
: 6 days
: EXCESS: 7000
: Repair / Reg 54 point

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT