

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En	Automobile	
MS	INCOME INSURAN	NCE LTD	Ref:	CS/INC24070141/Aqh3	
	75 BRAS BASAH F		Date:	25/09/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.		Policy Particulars :- THIRD PARTY CLAIM			
١.	Insured Veh.	SJP 4254E	Veh. Inspected	SJT 257C	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1284546-002	Excess	\$0.00	
	Assign From	NATALIE LEE	Assign Date	09/07/2024	
2.	Assign From		cle Details	03/01/2024	
- .	Make & Model	TOYOTA COROLLA ALTIS	C.C	1598	
	Engine No.	3ZZ4928424	Year of Reg.	22/09/2009	
	Chassis No.	MR053ZEE106154217	Colour	WHITE	
	Odometer	180216 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	BRIDGESTONE	6	
	L/H Front Tyre	195/65R15	BRIDGESTONE	6	
	R/H Rear Tyre	195/65R15	BRIDGESTONE	6	
	L/H Rear Tyre	195/65R15	BRIDGESTONE	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	28/06/2024	Inspection Date	11/07/2024 (13:02)	
	Survey held at				
5a.	n. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
5b.		Estimate	Days of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days