

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070142/AUA3Q2
Date: 09/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SMA8468Y Insured Vehicle No : GBD7993T
Date of Loss: 05/07/2024 Nature of Claim: TP Claim No: MFL2024D0009403

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA8468Y
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Engine No: G4FGJU185752
Reg. Date: 16/06/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU685817
Colour: Black Odometer: 163955 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,305.26	8,521.04	8,784.22	50.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	1,690.00	2,180.00	56.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,175.26	10,211.04	10,964.22	51.78
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	21,175.26	8,000.00	13,175.26	62.22
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		8,727.25		
Global Sum Settlement (S\$)		8,700.00		

INSPECTION

Date of Assignment: 08/07/2024
Date Inspected: 08/07/2024 Inspected At: Kt Motorwerk (HQ)
Singapore 489978
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2024)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA8468Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,280.00 FL	*1,740.00 FL
2	1		*BOOTLID INSULATOR	Not Necessary	198.00 FL	*- FL
3	1		*BOOTLID WEATHERSTRIP	Cut	198.60 FL	*198.60 FL
4	1		*BOOTLID HANDLE GARNISH	Deformed	476.70 FL	*285.00 FL
5	1		*BOOTLID INNERLOCK	Damaged	385.20 FL	*385.20 FL
6	2		*BOOTLID STOPPER	Not Necessary	70.00 FL	*- FL
7	1		*BOOTLID ELANTRA LOGO	Necessary	179.70 FL	*60.00 FL
8	1		*BOOTLID SPEC EMBLEM	Necessary	95.60 FL	*65.00 FL
9	1		*BOOTLID H EMBLEM	Necessary	106.00 FL	*62.00 FL
10	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	210.00 FL	*- FL
11	2		*BOOTLID LAMP	Cracked	1,191.60 FL	*805.00 FL
12	2		*TAILAMP	Cracked	1,397.00 FL	*1,197.00 FL
13	2		*TAILAMP INNER SEALER	Not Necessary	70.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	1,087.90 FL	*475.00 FL
15	1		*REAR BUMPER SMART KEY SENSOR	Damaged	345.30 FL	*195.00 FL
16	2		*REAR BUMPER RETAINERS	Not Necessary	316.60 FL	*- FL
17	1		*REAR BUMPER LOWER COVER	Torn	185.80 FL	*185.80 FL
18	2		*REAR BUMPER REFLECTOR	Not Necessary	491.60 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	640.70 FL	*329.00 FL
20	2		*REAR REINFORCEMENT TOP BRACKETS	Not Necessary	175.80 FL	*- FL
21	3		*REAR REINFORCEMENT BOTTOM BRACKETS	Not Necessary	268.50 FL	*- FL
22	2		*REAR BUMPER SENSORS	Damaged	496.44 FS	*200.00 FS
23	2		*REAR FENDER INNER TRIM	Torn	1,124.80 FL	*560.00 FL
24	1		*EXHAUST PIPE	Not Necessary	1,344.60 FL	*- FL
25	2		*EXHAUST MOUNTING	Not Necessary	136.00 FL	*- FL
26	2		*EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
27	1		*END PANEL	Dented	625.80 FL	*545.00 FL
28	1		*END PANEL TOP GARNISH	Deformed	198.60 FL	*198.60 FL
29	1		*SET REAR NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*50.00 FS
30	2		*SET TAILLAMP CLIPS	Not Necessary	60.00 FS	*- FS
31	2		*SET BOOTLID LAMPS CLIPS	Not Necessary	60.00 FS	*- FS
32	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
33	1		*SET REVERSE CAMERA	Damaged	450.00 FS	*380.00 FS
34	1		*SET REAR BUMPER DIFFUSER	Distorted	1,200.00 FS	*800.00 FS
35	1		*SET EXHAUST PIPE DUMMY TWIN	N/S Damaged	350.00 FS	*120.00 FS
36	1		*THIRD BRAKE LAMP	Not Necessary	450.00 FS	*- FS
37	1		*REAR SPOILER WITH LAMP	Cracked	980.00 FS	*600.00 FS
38	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
39	1		*ANTENNA ASSY -SMARTKEY INNER	Cracked	304.60 FL	*304.60 FL
40	1		*TOP BOARD	Deformed	344.80 FL	*298.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,756.24	10,098.80
- List Item Discount on L Items 10.00/20.00% (\$\$)	1,450.98	1,577.76
Total Parts (\$\$)	17,305.26	8,521.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAY PAINTING	New	1,400.00	800.00
3	CHECK WIRING ON TAILLAMPS	New	120.00	30.00
4	WIRING FOR THIRD BRAKE LAMP	New	80.00	0.00
5	WIRING FOR SPOILER	New	80.00	0.00
6	REMOVE AND INSTALL REVERSE CAMERA	New	120.00	50.00
7	REMOVE AND INSTALL EXHAUST SYSTEM	New	250.00	0.00
8	ANTI RUST	New	180.00	60.00
9	PROGRAMING ADAS SYSTEM	New	120.00	0.00
10	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (\$\$)			3,870.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >