

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

VEHICLE REPAIR ESTIMATE

Vehicle Number : SMA8468Y Date : 08.07.2024

Vehicle Model : HYUNDAI ELANTRA Chassis : KMHD841CMJU685
817

Accident Date : 05.07.2024 TP Ins. INDIA

Original Reg Date : 16.06.2018

ESTIMATE

1	1 pc	BOOTLID <i>Dented</i>		2,280.00	✓
2	1 pc	BOOTLID INSULATOR <i>new</i>		198.00	+
3	1 pc	BOOTLID WEATHERSTRIP <i>int</i>		198.60	✓
3	1 pc	BOOTLID HANDLE GARNISH <i>Dented</i>		476.70	285
4	1 pc	BOOTLID INNERLOCK <i>Dented</i>		385.20	✓
5	2 pc	BOOTLID STOPPER <i>new</i>	35.00	70.00	+
6	1 pc	BOOTLID "ELANTRA" LOGO <i>2</i>		179.70	60
7	1 pc	BOOTLID "SPEC" EMBLEM <i>1pc</i>		95.60	65
8	1 pc	BOOTLID "H" EMBLEM <i>✓</i>		106.00	62
8	1 pc	BOOTLID NUMBER PLATE LAMP <i>new</i>	105.00	210.00	+
9	2 pc	BOOTLID LAMP <i>broken</i>	595.80	1,191.60	805
10	2 pc	TAILAMP <i>broken</i>	698.50	1,397.00	1197
11	2 pcs	TAILAMP INNER SEALER <i>new</i>	35.00	70.00	+
12	1 pcs	REAR BUMPER <i>Broken</i>		1,087.90	475
13	1 pcs	REAR BUMPER SMART KEY SENSOR <i>Dented</i>		345.30	195
14	2 pcs	REAR BUMPER RETAINERS <i>new</i>	158.30	316.60	+
15	1 pcs	REAR BUMPER LOWER COVER <i>torn</i>		185.80	✓
16	2 pcs	REAR BUMPER REFLECTOR <i>new</i>	245.80	491.60	✓
17	1 pc	REAR BUMPER REINFORCEMENT <i>Dented</i>		640.70	329
18	2 pc	REAR REINFORCEMENT TOP BRACKETS <i>new</i>	87.90	175.80	+
19	3 pc	REAR REINFORCEMENT BOTTOM BRACKETS <i>new</i>	89.50	268.50	+
20	2 pc	REAR BUMPER SENSORS <i>Dented</i>	275.80	551.60	2w(SW)
21	2 pc	REAR FENDER INNER TRIM <i>torn</i>	562.40	1,124.80	560
22	1 pc	EXHUAUST PIPE <i>new</i>		1,344.60	+
23	2 pc	EXHUAUST MOUNTING <i>new</i>	68.00	136.00	+
24	2 pc	EXHUAUST GASKET <i>new</i>		60.00	+
25	1 pc	END PANEL <i>Dented</i>		625.80	545
26	1 pc	END PANEL TOP GARNISH <i>Dented</i>		198.60	✓

subtotal 14,412.00
less 10% 1,441.20
total 12,970.80

Special Nett

1	1 set	Rear Number Plate with Holder <i>Best</i>		50.00	✓
2	2 set	Tailamps clips <i>Not n</i>	30.00	60.00	+
3	2 set	bootlid lamps clips <i>Not n</i>	30.00	60.00	+
4	1 set	Bootlid inner trim clips <i>Not n</i>		30.00	+
5	1 set	Reverse Camera <i>Dryd</i>		450.00	380
6	1 set	Rear Bumper diffuser <i>Dishled</i>		1,200.00	800
7	1 set	Exhaust pipe Dummy Twin <i>2H End</i>		350.00	+ 120
8	1 pc	Third Brake Lamp <i>Not n</i>		450.00	+
9	1 pc	Rear Spoiler with Lamp <i>Not n</i>		980.00	+ 60
10	1 set	Body Panel Joint Sealant <i>Not n</i>		120.00	60

2010

Labour charge

Panel Beating		1,400.00	800 700
Spray painting		1,400.00	900 800
Check Wiring on tailamps		120.00	30
Wiring for third brake lamp		80.00	+
Wiring for spoiler		80.00	+
Remove and install reverse camera		120.00	50
Remove and install exhaust system		250.00	+
Anti rust		180.00	60
Programing ADAS system		120.00	+
Remove and install reverse sensor		120.00	50

1690

\$ 20,590.80

Adrian Lj

L/S 08/07/24.

06 Supp.

Supplementary: 298

Total: 10024.56

L/S: 8Kc

8Kc.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SMA8468Y	Date of Request	09.07.2024
Vehicle Model	Hyundai Elantra	Number of Days to Extend (If any)	1

S/N	PART DESCRIPTION		LIST PRICE
1	Antenna Assy-Smartkey Inner <i>Ant d</i>		<u>\$304.60</u>
2	Top Board <i>Det d</i>		\$344.80 ✓

298