



HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhhb.com.sg
Company Reg. No. 202341776E

Vehicle No.: SML8712J
Make/Model : Renault Scenic
Chassis no.: VF1RFA00262894719
Year of Manufacture : 2019

Date of survey:
Surveyor:
Company :
Ins Company : Income
TP vehicle No.: SBJ3773G

Hui Feng

Accident Date : 30 Jun 2024

Type of repair: Lump Sum

Estimate cost of repairs

Qty	Part Description	Unit Price	Total Price
1 pc	Front bumper <i>Rehd</i> x ✓	\$ 1821.00	\$ 1,821.00 <i>1620</i>
2 pcs	Front bumper retainer <i>new</i> x	\$ 180.00	\$ 360.00 x
1 pc	Front bumper top grille <i>new</i>	\$ 515.80	\$ 515.80 x
1 pc	Front bumper lower grille <i>Rehd</i> ✓	\$ 286.00	\$ 286.00 ✓
1 pc	Front bumper centre <i>new</i>	\$ 366.40	\$ 366.40 x
1 pc	Front bumper sensor <i>Rehd</i> ✓	\$ 291.00	\$ 291.00 ✓
1 pc	Foglamp cover <i>new</i> x	\$ 321.00	\$ 320.00 x
1 pc	Foglamp chrome cover <i>new</i> x. <i>new</i>	\$ 318.00	\$ 318.00 x
1 pc	Front bonnet <i>Rehd</i> ✓	\$ 1,465.00	\$ 1,465.00 ✓
1 pc	Front bumper reinforcement <i>new</i>	\$ 844.00	\$ 844.00 x
1 pc	Rear bumper top <i>Rehd</i> ✓	\$ 1,755.00	\$ 1,755.00 ✓
1 pc	Rear bumper bottom <i>Rehd</i> ✓	\$ 502.30	\$ 502.30 ✓
1 pc	Rear bumper silver garnish <i>Rehd</i> ✓	\$ 685.00	\$ 685.00 ✓
1 pc	Rear bumper reflector <i>LH missing</i> ✓	\$ 268.00	\$ 536.00 <i>268.</i>
2 pcs	Rear bumper retainer <i>new</i>	\$ 196.00	\$ 392.00 x
1 pc	Rear bumper lower skirt <i>Rehd</i> ✓	\$ -	- With Rear bumper
2 pcs	Rear reverse sensor side <i>new</i>	\$ 291.00	\$ 582.00 x
4 pcs	Rear reverse sensor <i>3 pieces x dried</i>	\$ 291.00	\$ 1,164.00 <i>(3 pieces) 873.</i>
1 pc	Tailgate <i>Distorted</i> ✓	\$ 3,617.20	\$ 3,617.20 <i>3014.</i>
1 pc	Tailgate logo "Renault" ✓	\$ 142.30	\$ 142.30 ✓
1 set	Tailgate emblem "Renault" ✓	\$ 116.20	\$ 116.20 ✓
1 set	Tailgate emblem "SCENIC" ✓	\$ 102.10	\$ 102.10 ✓
1 pc	Tailgate inner trimboard <i>new</i> ✓	\$ 402.10	\$ 402.10 ✓
2 pcs	Tailgate damper <i>new</i> x	\$ 285.00	\$ 570.00 x
1 set	Rear number plate lamp <i>new</i>	\$ 121.00	\$ 121.00 x
1 pc	Rear windscreen moulding <i>new</i> ✓	\$ 231.00	\$ 231.00 ✓
2 pcs	Tailgate lamp <i>new</i> ✓	\$ 616.00	\$ 1,232.00 ✓
1 pc	Tail lamp LH <i>new</i>	\$ 657.00	\$ 657.00 x
1 pc	Rear end panel <i>Rehd</i> ✓	\$ 788.00	\$ 788.00 ✓
1 pc	Rear end panel top cover <i>Rehd</i> ✓	\$ 296.90	\$ 296.90 ✓

Supplementary

- 1) Rear floor panel lower cover
- 2) rear bumper reinforcement
- 3) rear bumper inner bracket



HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhhb.com.sg
Company Reg. No. 202341776E

13549.90

12194.91

Less 10%

\$ -
\$ -

- 1 set Front bumper clips *2 per*
1 set Rear bumper clips
1 set Tailgate trimboard clips *1 set*
2 set Front/Rear number plate with casing *Best*
1 set Rear windscreen sticker "tribecar" *1 set*
1 set Rear windscreen sealant *1 set*

\$ 50.00 SN *30*
\$ 50.00 SN *30*
\$ 50.00 SN *30*
\$ 100.00 SN *✓*
\$ 120.00 SN *✓*
\$ 60.00 SN *✓*
\$ 430.00

250

- 1 job To remove, refix tailgate windscreen glass.

\$ 120.00 *✓*

- 1 job To remove, transfer & refix tailgate fittings.

\$ 100.00 *60*

- 1 job To remove & renew reverse sensors.

\$ 80.00 *50*

- 1 job To remove & refit back-up camera.

\$ 80.00 *50*

- 1 job Wiring charges

\$ 80.00 *60*

2600

- 1 job Tuff kote

\$ 100.00 *60*

- 1 job To putty and respray painting

\$ 1,400.00 *1000*

- 1 job Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.

\$ 1,400.00 *1200*

\$ 3,360.00

Grand-total

\$ 3,790.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary: 1410.66

Total 16455.57

H/S: 13.11C

Adrian G

H/S 09/07/24

12 Days



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921

Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhbhm.com.sg

Company Reg. No. 202341776E

Vehicle No.: SML8712J
Make/Model : Renault Scenic
Chassis no.: VF1RFA00262894719
Year of Manufacture : 2019

Date of survey:
Surveyor:
Company :
Ins Company : Income
TP vehicle No.: SBJ3773G

Accident Date : 30 Jun 2024

Type of repair: Lump Sump

Supplementary

Qty	Part Description	Unit Price	Total Price
1 pc	Rear floor panel lower cover <i>torn ✓</i>	\$ 615.40	\$ 615.40
1 pcs	Rear bumper reinforcement <i>Deord ✓</i>	\$ 320.10	\$ 320.10
1 pc	Rear bumper inner bracket <i>and ✓</i>	\$ 755.00	\$ 755.00 310
1 pc	Rear exhaust heat shield <i>Cracked ✓</i>	\$ 321.90	\$ 321.90

Adnan J L
12/07/24.

Grand-total

1567.40

Supplementary: 1410.66