



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 91399389

TAX INVOICE

Repair Code : CLM18243
Date in : 16/05/2024
Vehicle Num. : SMT2169A
Model : TOYOTA NOAH HYBRID 1.8X CVT
Chassis/Eng# : ZWR800429371/2ZR2G48886

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR SIDE MIRROR <i>cut</i>	1	1636.90	1,636.90
FRONT RH DOOR SIDE MIRROR COVER <i>awked</i>	1	132.70	132.70
Subtotal before discount			1,769.60
Percentage discount 25%			442.40
Sub-total 1			1,327.20
Parts-total			1,769.60

LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total	680.00
Parts & Labour Total	2,449.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

*** This is a computer-generated document which requires no signature. ***

page 1

Adam G
c/s 06/07/24
01 Day