

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401036
INV Date : 17-10-2024

Reference CD/FCI24070148/Rua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNP 9768J
Insured Veh. SHA 7186B
Claim No. D24005913MFCT
Policy No. D-24101861MFCT
Accident Date 05/07/2024
Inspection Date 09/07/2024

Description	Amount
Third Party Express Settlement	350.00
Sub-Total	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24070148/Rua3q2
16 RAFFLES QUAY	Date:	17/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHA 7186B	Veh. Inspected	SNP 9768J
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005913MFCT	Excess	\$0.00
Assign From	CHRIS LIM	Assign Date	08/07/2024

2. Vehicle Details

Make & Model	HYUNDAI SX2 KONA 1.6 GDI HEV SR	C.C	1580
Engine No.	G4LLPS264781	Year of Reg.	25/03/2024
Chassis No.	KMHHE811VRU037034	Colour	RED
Odometer	7073 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55 R18	NEXEN	6
L/H Front Tyre	215/55 R18	NEXEN	6
R/H Rear Tyre	215/55 R18	NEXEN	6
L/H Rear Tyre	215/55 R18	NEXEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2024	Inspection Date	09/07/2024
Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 9768J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	FRONT BUMPER CLIP	NECESSARY	\$20.00	\$20.00
1	COVER ASSY-FR BUMPER UPR	TO REPAIR SEE LABOUR	\$726.00	\$0.00
1	COVER ASSY-FR BUMPER LWR	SCRATCHED	\$1,100.00	\$1,100.00
1	BRACKET ASSY -FR BUMPER SIDE LH	SERVICEABLE	\$20.00	\$0.00
1	BRACKET ASSY-FR BUMPER SIDE RH	SERVICEABLE	\$20.00	\$0.00
1	LAMP ASSY -HEAD LH	SCRATCHED	\$2,759.00	\$2,759.00
3	CLIP	NECESSARY	\$3.00	\$3.00
1	GUARD ASSY -FRONT WHEEL LH	SERVICEABLE	\$175.00	\$0.00
1	MOULDING FRONT BUMPER LH	SERVICEABLE	\$74.00	\$0.00
1	CARRIER ASSY -FRONT END MODULE	CRACKED	\$1,051.00	\$1,051.00
	LESS 20.00% DISCOUNT		(\$1,189.60)	(\$986.60)
			\$4,758.40	\$3,946.40
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$40.00	\$20.00
			\$40.00	\$20.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CARRY OUT ACCIDENT BODY REPAIR -FRONT BUMPER.INCLUSIVE OF THE REPAIR OF COVER ASSY -FR BUMPER UPR.		\$1,260.00	\$1,260.00
	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS-FRONT BUMPER/FRONT BUMPER GARNISH		\$1,050.00	\$700.00
	TO REALIGN BOTH FRT HEADLAMP		\$40.00	\$40.00
	TO CHECK FOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER AC		\$180.00	\$180.00
	TO REPROGRAMME AFTER ACCIDENT REPAIR		\$180.00	\$180.00
			\$2,710.00	\$2,360.00
GRAND TOTAL			\$7,508.40	\$6,326.40
	RECOMMENDED COST OF REPAIRS			\$6,326.40
Report Ref No: CD/FCI24070148/Rua3q2				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J




PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J




PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J



PHOTOGRAPHS FOR VEHICLE NO. : SNP 9768J

