

**Trans-cab Auto Services Pte Ltd**

AAD2404-042

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5688S

Steve (LKK) Steve chen@lkkauto.com  
+6 919-9429541

Vehicle No.: 9/7/24, 4. MP  
 Chassis No.: m R  
 UEN No:  
 Vehicle Make: L/S  
 Vehicle Model:  
 Date of Accident: M 12 sy  
 Third Party Insurer:  
 Date of Registration: 3 days

SHD5688S

JTDKB3FU503079341

200303878K

TOYOTA

PRIUS

8/4/2024

SHD2663H/

17/1/2019

**PART****LIST**

1	PANEL SUB-ASSY, FRONT DOOR, LH / ON	\$	1,641.36
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH X	\$	243.81
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH X	\$	493.40
1	WEATHERSTRIP, FRONT DOOR, LH X	\$	292.32
1	HINGE ASSY, FRONT DOOR, LOWER LH X	\$	139.86
1	HINGE ASSY, FRONT DOOR, UPPER LH X	\$	123.06
1	TAPE, BLACK OUT, NO.1 FRT LH / R	\$	16.91
1	TAPE, BLACK OUT, NO.2 FRT LH / R	\$	55.02
1	TAPE, BLACK OUT, NO.3 FRT LH / R	\$	33.29
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH X	\$	1,161.83
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH X	\$	300.62
1	PANEL SUB-ASSY, REAR DOOR, LH X R	\$	1,634.33
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH X	\$	243.81
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH X	\$	123.06
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH X	\$	369.60
1	HINGE ASSY, REAR DOOR, LOWER LH X	\$	109.62
1	HINGE ASSY, REAR DOOR, UPPER LH X	\$	124.74
1	TAPE, BLACK OUT, NO.1 REAR LH X	\$	27.62
1	TAPE, BLACK OUT, NO.2 REAR LH X	\$	44.00
1	TAPE, BLACK OUT, NO.3 REAR LH X	\$	19.43
1	COVER, REAR BUMPER X	\$	612.68
1	REAR BUMPER SIDE RETAINER LH X	\$	167.48
1	SEAL, REAR BUMPER SIDE, LH X	\$	149.21
1	PANEL SUB-ASSY, QUARTER, LH X	\$	1,099.46
1	LINER, REAR WHEEL HOUSE, LH X	\$	176.09

ALL X = NN

**Trans-cab Auto Services Pte Ltd**

AAD2404-042

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD56885

1	MOULDING ASSY, BODY ROCKER PANEL, LH X R	\$	624.54
<b>TOTAL</b>		\$	<b>10,027.14</b>
<b>25%</b>		\$	<b>2,506.79</b>
		\$	<b>7,520.36</b>

**Special Nett**

2SET	DOOR TRIM CLIP X	\$	70.00	
2SET	DOOR WEATHERSTRIP CLIP X	\$	130.00	
1	DOOR STICKER TRANSCAB / NR	\$	100.00	80
1	DOOR STICKER TEL NO. / NR	\$	100.00	80
1	TYRE X	\$	350.00	
1SET	CLIP, ROCKER PANEL MOULDING X	\$	65.00	
1SET	FENDER CLIP X	\$	130.00	
1	FENDER LINER CLIP X	\$	65.00	
<b>TOTAL</b>		\$	<b>1,010.00</b>	

ALL X = NN

**TOTAL PARTS \$ 2,300.00****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	20
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	50
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	250
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	600
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	30

**Trans-cab Auto Services Pte Ltd**

AAD2404-042

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5688S

To check steering geometry and computer wheel alignment \$ 220.00 X

To remove and refit of rear fender fittings, attachment and perform water seepage test. \$ 170.00 X

**TOTAL \$ 4,550.00**

**Over All Total \$ 14,370.36**

**(PART-BY-PART) Repair Days****08 Days****ALL X = NN**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_